



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SLX 9284U

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	PANEL SET,R.SIDE (SN)	DENTED	157.88
1	PANEL COMP,R.RR.DOOR (SN)	DENTED	497.38
1	TAPER.RR.DOOR SASH (SN)	NECESSARY	10.01
1	WHEEL,DISK AL 15X7 (SN)	DAMAGED	310.50
1	SUNDRIES (SN)	NECESSARY	20.00
			995.77
<u>LABOUR</u>			
WHEEL ALIGNMENT X4.			144.00
BODY JOINT SEALANT.			80.00
BODY UNDERSIDE COATING.			100.00
APPLY BODY UNDERSIDE COATING.			250.00
RESET VEHICLE SMART ENTRY SYSTEM.			224.00
REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST.			280.00
CUT OFF & RENEW R SILL PANEL. STRAIGHTEN ALIGN.			1,440.00
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)			840.00
			3,358.00
GRAND TOTAL			4,353.77

RECOMMENDED COST OF REPAIRS	4,353.77
------------------------------------	-----------------

Report Ref No. CS1/SPF22005989/Ucy3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.