

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005993/RCY3Q2**Date:** 19/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00183752100
Claimant Vehicle No :	SNE4902D	Insured Vehicle No :	SJR6299C
Date of Loss:	21/06/2022	Nature of Claim:	TP
		Claim No:	SNM22D204375/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE4902D		
Make & Model:	TOYOTA COROLLA ALTIS, 1.8 E HYBRID ELEGANCE (2WD) (A)	Engine No:	2ZRY791310
Reg. Date:	18/03/2022 (Man. Year: 2021)	Chassis No:	MR2BZ3BE200008702
Colour:	Grey	Odometer:	17932 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,695.00	6,558.12	7,136.88	52.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	2,900.00	1,000.00	25.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,595.00	9,458.12	8,136.88	46.25
Approved Total (Overridden) (S\$)		7,550.00		
(S\$)	17,595.00	7,550.00	10,045.00	57.09
+ GST 7.00/7.00% (S\$)	1,231.65	528.50	703.15	57.09
Nett Amount (S\$)	18,826.65	8,078.50	10,748.15	57.09

INSPECTION

Date of Assignment:	23/06/2022	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Date Inspected:	23/06/2022 Inspected At:	
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD RASUL**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Sep 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.8 E HYBRID ELEGANCE (2WD) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNE4902D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,125.00 FL	*905.20 FL
2	1		*BOOTLID INNER TRIM	Not Necessary	359.00 FL	*- FL
3	2		*BOOTLID REFLECTOR C/W CHROME	Cracked	912.00 FL	*456.00 FL
4	4		*BOOTLID STOPPER	Necessary	300.00 FL	*128.00 FL
5	1		*BOOTLID TOP LOCK	Bent	398.00 FL	*256.00 FL
6	1		*BOOTLID TOP LOCK COVER	Deformed	68.00 FL	*68.00 FL
7	1		*BOOTLID OUTER CHROME MOULDING CENTRE	Cracked	312.00 FL	*312.00 FL
8	1		*BOOTLID LOWER LOCK	Bent	39.00 FL	*39.00 FL
9	1		*BOOTLID WEATHERSTRIP	Necessary	220.00 FL	*220.00 FL
10	1		*BOOTLID LOGO	Necessary	74.00 FL	*58.60 FL
11	1		*BOOTLID EMBLEM ALTIS	Necessary	65.00 FL	*60.20 FL
12	1		*BOOTLID SENSOR	Cracked	312.00 FL	*280.00 FL
13	1		*BOOTLID EMBLEM COROLLA	Necessary	65.00 FL	*60.20 FL
14	2		*BOOTLID NUMBER PLATE LAMP	Not Necessary	124.00 FL	*- FL
15	2		*TAILAMP C/W CHROME	Cracked	1,224.00 FL	*845.00 FL
16	2		*TAILAMP LOWER PANEL	Bent	644.00 FL	*405.80 FL
17	1		*REAR BUMPER	Cracked	698.00 FL	*581.00 FL
18	2		*REAR BUMPER SIDE RETAINER	Not Necessary	224.00 FL	*- FL
19	2		*REAR BUMPER BRACKET	Bent	326.00 FL	*326.00 FL
20	2		*REAR BUMPER SENSOR	Not Working	571.50 FS	*200.00 FS
21	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	587.00 FL	*- FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	395.00 FL	*332.70 FL
23	2		*REAR BUMPER REFLECTOR	Not Necessary	224.00 FL	*- FL
24	1		*REAR BUMPER UNDERCOVER	Not Necessary	315.00 FL	*- FL
25	1		*AIR VENT	Not Necessary	65.00 FL	*- FL
26	2		*REAR FENDER	Repair	2,048.00 FL	*- FL
27	2		*REAR FENDER COWLING	Not Necessary	716.00 FL	*- FL
28	2		*REAR FENDER INNER TRIM	Deformed	796.00 FL	*758.00 FL
29	1		*REAR WINDSCREEN MOULDING	Not Necessary	112.00 FL	*- FL
30	1		*REAR END PANEL	Bent	695.00 FL	*617.00 FL
31	1		*END PANEL TOP GARNISH	Deformed	278.00 FL	*240.00 FL
32	1		*REAR FLOOR PANEL	Bent	1,025.00 FL	*937.00 FL
33	1		*REAR SPARE TYRE TOP BOARD	Deformed	357.00 FL	*291.80 FL
34	1		*REAR SPARE TYRE TOP SPONGE	Not Necessary	358.00 FL	*- FL
35	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	398.00 FL	*- FL
36	1		*REAR NUMBER PLATE	Bent	50.00 FS	*35.00 FS
37	1		*BOOTLID INSULATOR CLIPS	Necessary	30.00 FS	*30.00 FS
38	1		*SET TAILAMP CLIPS	Necessary	40.00 FS	*20.00 FS
39	1		*REAR FENDER SEALANT	Not Necessary	150.00 FS	*- FS
40	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
42	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
44	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
45	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
46	1		*REAR SPARE TYRE PANEL SEALANT	Necessary	150.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
47	1		*REVERSE CAMERA	Not Necessary	400.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	17,659.50	8,602.50
					- List Item Discount on L Items 25.00/25.00% (\$\$)	3,964.50	2,044.38
					Total Parts (\$\$)	13,695.00	6,558.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,300.00
2	PAINT BEATING ON AFFECTED AREAS	New	1,600.00	1,300.00
3	REMOVE AND REFIR REAR BOOTLID MECHANISM	New	100.00	60.00
4	REMOVE AND REFIR REAR EXHAUST SYSTEM	New	150.00	0.00
5	REMOVE AND REFIR REVERSE SENSOR	New	100.00	60.00
6	REAR CHASSIS ALIGNMENT	New	200.00	100.00
7	TO CHECK ELECTRICAL WIRING	New	100.00	30.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	50.00	50.00
Gross Labour Cost (\$)			3,900.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >