

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22005995/ECY3M4**Date:** 08/08/2022**REFERENCE**

Insured/Claimant: MASINDO LOGISTIC PTE LTD Policy No: SPMF1000000465
Date of Loss: 20/06/2022 Nature of Claim: OD Claim No: MLPAISCL2022-00051JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE1714G**
Make & Model: UD TRUCKS ESCOT V, 10.8 D GKB5ELDHNT (M) Engine No: GH11734579
Reg. Date: 03/05/2016 (Man. Year: 2016) Chassis No: JNCM1F1A9GU006045
Colour: Grey Odometer: 336940 km
Engine Capacity: 10837 cc
Market Value/New Car Price: S\$72,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 (D/D) Rear Tyre Size: 295/80 R11.5 (D/D)
Front Left Side: Bridgestone 4/4 mm Rear Left Side: Bridgestone 4/4 mm
Front Right Side: Bridgestone 4/4 mm Rear Right Side: Bridgestone 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	57,463.00	56,112.00	1,351.00	2.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,580.00	6,400.00	6,180.00	49.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	70,043.00	62,512.00	7,531.00	10.75
Approved Total (Overridden) (S\$)		50,000.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	68,043.00	48,000.00	20,043.00	29.46
+ GST 7.00/7.00% (S\$)	4,763.01	3,360.00	1,403.01	29.46
Nett Amount (S\$)	72,806.01	51,360.00	21,446.01	29.46

INSPECTION

Date of Assignment: 23/06/2022

Date Inspected: 24/06/2022 Inspected At:

NLT VEHICLE SERVICE PTE LTD (HQ)
NO 2 BUROH CRESCENT, #02-10 ACE
@BUROH
Singapore 627546

Estimated Period of Repair: 14.0 days

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Aug 2022)	
Parts:	N/A	UD TRUCKS ESCOT V 10.8 D GKB5ELDHNT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE1714G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CABIN	Dented	45,000.00 FL	*45,000.00 FL
2	1		*FRONT BONNET	Dented	3,250.00 FL	*3,250.00 FL
3	1		*LOGO EMBLEM	Broken	250.00 FL	*250.00 FL
4	1		*ANTI ROLL BAR	Bent	2,850.00 FL	*2,850.00 FL
5	1		*ANTI ROLL BAR BRACKET (2PCS)	Bent	1,700.00 FL	*850.00 FL
6	1		*RADIATOR ASSY	Bent	2,500.00 FL	*2,500.00 FL
7	1		*INTER-COOLER ASSY	Bent	7,800.00 FL	*7,800.00 FL
8	1		*FRONT BUMPER INNER	Bent	2,200.00 FL	*2,200.00 FL
9	1		*FRONT BUMPER CENTER	Bent	1,250.00 FL	*1,250.00 FL
10	1		*LH SIDE BUMPER	Bent	550.00 FL	*550.00 FL
11	1		*LH HEAD LAMP	Broken	950.00 FL	*950.00 FL
12	1		*LH FOG LAMP	Broken	220.00 FL	*220.00 FL
13	1		*LH SIGNAL LAMP	Broken	180.00 FL	*180.00 FL
14	2		*CABIN ABSORBER (4PCS)	Bent	1,400.00 FL	*700.00 FL
15	3		*CABIN AIR BELLOW (4PCS)	Crushed	1,520.00 FL	*1,140.00 FL
16	1		*LH STEP BRACKET	Bent	450.00 FL	*450.00 FL
17	1		*SET AIRCON	Bent	2,800.00 FL	*2,800.00 FL
18	1		*WIPER TANK	Crushed	650.00 FL	*650.00 FL
19	1		*LH MIRROR ARM	Bent	420.00 FL	*420.00 FL
20	1		*MIRROR ARM MOTOR	Broken	1,850.00 FL	*1,850.00 FL
21	2		*LH MIRROR ARM BRACKET	Bent	560.00 FL	*560.00 FL
22	3		*LH SIDE MIRROR	Broken	540.00 FL	*540.00 FL
23	1		*ENGINE FAN ASSY C/W FAN CLUTCH	Bent	3,200.00 FL	*3,200.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	82,090.00	80,160.00
- List Item Discount on L Items 30.00/30.00% (\$\$)	24,627.00	24,048.00
Total Parts (\$\$)	57,463.00	56,112.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ACCIDENT REPAIR AND REPLACE THE ABOVE MENTIONED PARTS (21 DAYS X \$480EA)	New	10,080.00	4,500.00
2	TO APPLY PUTTY, PRIMER AND DO SPRAY PAINTING ON ALL AFFECTED AREA	New	2,500.00	1,900.00
Gross Labour Cost (\$\$)			12,580.00	6,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >