

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006001/EQY3M4**Date:** 19/07/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00110992101

**Claimant Vehicle
No :** SKQ5676Y**Insured Vehicle
No :** GBG5773J

Date of Loss: 17/06/2022

Nature of Claim: TP

Claim
No: SNM22D204266/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKQ5676Y**

Make & Model: MERCEDES-BENZ A180 R17, 1.6 (A)

Engine No: 27091030516557

Reg. Date: 10/12/2014 (Man. Year: 2014)

Chassis No: WDD1760422J326316

Colour: Red

Odometer: 117029 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 4,467.15 | 2,776.28 | 1,690.87 | 37.85 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,130.00 | 650.00 | 480.00 | 42.48 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,597.15 | 3,426.28 | 2,170.87 | 38.79 |
| Approved Total (Overridden) (S\$) | | 2,750.00 | | |
| (S\$) | 5,597.15 | 2,750.00 | 2,847.15 | 50.87 |
| + GST 7.00/7.00% (S\$) | 391.80 | 192.50 | 199.30 | 50.87 |
| Nett Amount (S\$) | 5,988.95 | 2,942.50 | 3,046.45 | 50.87 |

INSPECTION

Date of Assignment: 23/06/2022

Date Inspected: 27/06/2022 Inspected At:

15 FAN YONG ROAD

SINGAPORE 629792

REPAIRER: MOVA AUTOMOTIVE PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 19 Jul 2022) |
| Parts: | 144 | MERCEDES-BENZ A180 R17 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKQ5676Y) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|---|-----------------------------------|
| 1 | 1 | | *REAR BUMPER | Broken | 1,904.50 FL | *1,421.50 FL |
| 2 | 2 | | *REAR BUMPER RETAINER LH & RH | Not Necessary | 84.00 FL | *- FL |
| 3 | 2 | | *REAR BUMPER SENSOR (4PC) | Shorted | 1,540.00 FL | *606.60 FL |
| 4 | 4 | | *REAR BUMPER SENSOR RING | Necessary | 52.00 FL | *52.00 FL |
| 5 | 10 | | *REAR BUMPER CLIPS | Necessary | 95.00 FL | *30.00 FL |
| 6 | 1 | | *REAR BUMPER LOWER GARNISH | Cut | 356.00 FL | *356.00 FL |
| 7 | 1 | | *RR BUMPER CENTER SUPPORT 176 885 0065 | Not Necessary | 132.00 FL | *- FL |
| 8 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 715.00 FL | *565.66 FL |
| 9 | 1 | | *TOW EYE | Broken | 85.00 FL | *53.00 FL |
| | | | | | | F=Franchise part. L=ListItemDisc. |
| | | | | | Sub Total (S\$) | 4,963.50 |
| | | | | | - List Item Discount on L Items 10.00/10.00% (S\$) | 496.35 |
| | | | | | Total Parts (S\$) | 4,467.15 |
| | | | | | | 3,084.76 |
| | | | | | | 308.48 |
| | | | | | | 2,776.28 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO REPLACE REAR BUMPER & REAR BUMPER REINFORCEMENT, TO PANEL BEAT, REPAIR REAR END PANEL & REALIGN ALL CONNECTION | New | 450.00 | 250.00 |
| 2 | TO SPRAY PAINT ON REAR BUMPER, BUMPER SENSOR & END PANEL | New | 450.00 | 250.00 |
| 3 | TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS | New | 50.00 | 30.00 |
| 4 | TO CODING REAR BUMPER PDC SENSOR | New | 180.00 | 120.00 |
| Gross Labour Cost (\$) | | | 1,130.00 | 650.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >