

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22006005/KQY3Q2**Date:** 12/08/2022REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SMR3565T**Insured Vehicle No :** SJE1464T

Date of Loss: 21/06/2022

Nature of Claim: TP

Claim No: DMPC2200255H

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMR3565T**

Make & Model: HONDA FREED, 1.5 (A)

Engine No: LEB5620327

Reg. Date: 30/12/2019 (Man. Year: 2018)

Chassis No: GB71083263

Colour: Metallic Black

Odometer: 66610 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17

Rear Tyre Size:

215/45Z R17

Front Left Side: Pirelli 2 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 2 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,663.60	1,983.20	4,680.40	70.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	775.00	1,575.00	67.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,013.60	2,758.20	6,255.40	69.40
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	9,013.60	2,200.00	6,813.60	75.59
+ GST 7.00/7.00% (S\$)	630.95	154.00	476.95	75.59
Nett Amount (S\$)	9,644.55	2,354.00	7,290.55	75.59

INSPECTION

Date of Assignment: 23/06/2022

Date Inspected: 01/07/2022 Inspected At:

Yee Auto Pte Ltd (HQ)

160 SIN MING DRIVE, #02-17 SIN MING

AUTOCITY

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Aug 2022)
Parts:	M1-MPV	HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR3565T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent / Cracked	1,185.30 F	*1,050.00 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	64.00 F	*64.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	525.60 F	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	122.40 F	*- FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	122.40 F	*- FL
6	1		*FRONT FENDER -RH	Repair	798.60 F	*- FL
7	1		*FRONT FENDER LOGO	Necessary	85.50 F	*85.50 FL
8	1		*FRONT FENDER SPLASH SHIELD -RH	Serviceable	178.10 F	*- FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 F	*- FL
10	1		*FRONT KNUCKLE ARM -RH	Bent	428.70 F	*360.80 FL
11	1		*FRONT LOWER ARM-RH	Distorted	298.60 F	*298.60 FL
12	1		*FRONT WHEEL BEARING -RH	Necessary	295.10 F	*295.10 FL
13	1		*HEAD LAMP -RH	Serviceable	1,985.10 F	*- FL
14	1		*HEAD LAMP LOWER BRACKET-RH	Serviceable	89.10 F	*- FL
15	1		*FRONT SHOCK ABSORBER -RH	Bent	425.10 F	*325.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,663.60	2,479.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	495.80
Total Parts (S\$)	6,663.60	1,983.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,000.00	300.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,000.00	400.00
3	TO APPLY RUST PROOFING ON REPAIRED ,REPLACED PANEL	New	150.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	80.00	15.00
5	WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$)			2,350.00	775.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >