



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 5960K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	GLASS, WINDSHIELD (SN)	CRACKED	759.38	759.38
1	WEATHERSTRIP, WINDSHIELD (SN)	NECESSARY	292.74	292.74
1	GARNISH, FR PANEL (SN)	CUT	465.80	465.80
1	GRILLE, RADIATOR (SN)	CRACKED	307.78	307.78
1	PANEL, CAB FR CORNER - LH (SN)	CRACKED	412.31	412.31
1	PANEL, CAB FR CORNER - RH (SN)	CRACKED	412.31	412.31
1	CAP, MIRROR COVER RH (SN)	MISSING	32.67	32.67
1	PILLAR, FR RH (SN)	TO REPAIR SEE LABOUR	1,204.95	-
1	MARK, CANTER (SN)	NECESSARY	86.30	86.30
1	MARK, THREE-DIA (SN)	NECESSARY	67.25	67.25
1	PANEL ASSY, FRONT (SN)	BENT	2,124.59	2,124.59
1	STAY, RR VIEW MIRROR - LH (SN)	BENT	373.41	373.41
1	MIRROR, UNDER VIEW (SN)	CRACKED	45.26	45.26
1	COVER, FR BMPR CORNER, LH (SN)	SCRATCHED	275.44	275.44
1	COVER, FR BUMPER CORNER, RH (SN)	SCRATCHED	275.44	275.44
1	GARNISH, HEADLAMP, LH (SN)	MISSING	141.75	141.75
1	GARNISH, HEADLAMP, RH (SN)	NOT NECESSARY	141.75	-
1	LAMP ASSY, TURN SIGNAL, FR LH (SN)	BROKEN	171.95	171.95
1	LAMP ASSY, TURN SIGNAL, FR RH (SN)	BROKEN	171.95	171.95
1	HEADLAMP ASSY, LH (SN)	CRACKED	522.68	522.68
1	HEADLAMP ASSY, RH (SN)	CRACKED	522.68	522.68
1	ARM W/SHLD WIPER (SN)	CRACKED	91.13	91.13
1	BLADE ASSY, WIPER (SN)	NECESSARY	39.58	39.58
1	HEATER ASSY (SN)	NOT NECESSARY	2,207.18	-
1	DUCT, AIR CLEANER INTAKE (SN)	NOT NECESSARY	593.09	-
1	IU BRACKET (SN)	NECESSARY	15.00	15.00
1	COMPANY STICKER (SN)	NECESSARY	200.00	150.00
1	COVER, RR VIEW MIRROR STAY (ADDITIONAL) (SN)	MISSING	11.30	11.30
1	LINK, W/SHLD WIPER (ADDITIONAL) (SN)	CRACKED	268.97	268.97
			12,234.64	8,037.67

Report Ref No. CS/UOI22006009/Rvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REFIX FRONT WINDSCREEN.		150.00	120.00
	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC. INCLUSIVE OF THE REPAIR OF PILLAR, FR RH.		4,000.00	2,700.00
	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK.		180.00	150.00
	REFIX AIRCON SYSTEM AND TOP UP GAS. TO CHECK FUNCTION.	NOT NECESSARY	700.00	-
	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC.		2,000.00	1,400.00
	TO REMOVE AND INSTALL MOBILEYE.		350.00	350.00
	TO REMOVE AND REFIX FRONT DASHBOARD.	NOT NECESSARY	700.00	-
			8,080.00	4,720.00
GRAND TOTAL			20,314.64	12,757.67

RECOMMENDED COST OF REPAIRS			12,757.67
LESS EXCESS			-500.00
NETT LIABILITY			12,257.67

Report Ref No. CS/UOI22006009/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.