

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006012/AYA3Q2
Date: 20/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220029971
Claimant Vehicle No :	GBH8212L	Insured Vehicle No :	SLL3373Z
Date of Loss:	16/06/2022	Nature of Claim:	TP
		Claim No:	5989904754SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH8212L	Engine No:	1KD2827103
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 4DR (A)	Chassis No:	JTFHT02P000245263
Reg. Date:	02/10/2018 (Man. Year: 2018)	Odometer:	59371 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,769.47	3,846.27	923.20	19.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	2,020.00	760.00	27.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,549.47	5,866.27	1,683.20	22.30
Approved Total (Overridden) (S\$)		4,700.00		
	(S\$)	7,549.47	4,700.00	2,849.47
+ GST 8.00/8.00% (S\$)	603.96	376.00	227.96	37.74
Nett Amount (S\$)	8,153.43	5,076.00	3,077.43	37.74
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,720.00		

INSPECTION

Date of Assignment:	23/06/2022	
Date Inspected:	23/06/2022 Inspected At:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,262.20 FL	*2,139.00 FL
2	1		*BOOT LID LOGO	Necessary	72.20 FL	*72.20 FL
3	1		*BOOT LID RUBBER	Cut	368.90 FL	*368.90 FL
4	1		*BOOT LID LOCK	Damaged	349.60 FL	*349.60 FL
5	1		*BOOT LID LOCK CHECKER	Not Necessary	65.90 FL	*- FL
6	1		*BOOTLID TRIM	Not Necessary	210.50 FL	*- FL
7	1		*BOOT LID TOYOTA STICKER	Necessary	39.90 FL	*39.90 FL
8	1		*BOOT LID HIACE EMBLEM	Necessary	39.90 FL	*39.90 FL
9	1		*REAR PANEL INNER	Repair	398.00 FL	*- FL
10	1		*REAR PANEL (OUTER)	Dented	481.30 FL	*481.30 FL
11	1		*REAR PANEL TRIM	Bent	138.00 FL	*138.00 FL
12	1		*REAR BUMPER	Deformed	373.10 FL	*373.10 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	79.80 FL	*79.80 FL
14	1		*SET BOOT LID SPIRIT OF ENTERPRISE FACEBOOK, TRIPADVISOR STICKER	Necessary	380.00 FS	*280.00 FS
15	1		*BOOT LID BONDING THROUGH THE POWER OF FUN STICKER	Necessary	250.00 FS	*180.00 FS
16	1		*70KM/H STICKER	Necessary	30.00 FS	*15.00 FS
17	1		*SET BOOTLID TRIM CLIPS	Not Necessary	40.00 FS	*- FS
18	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*40.00 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
20	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
21	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,989.30	4,866.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,219.83	1,020.43
Total Parts (\$\$)	4,769.47	3,846.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REPLACE STICKERS	New	100.00	50.00
3	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
4	TO REMOVE AND REFIT THIRD BRAKE LIGHT	New	80.00	0.00
5	TO REMOVE AND REFIT REVERSE CAMERA	New	80.00	50.00
6	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
7	TO SPRAY PANEL SEALANT	New	120.00	60.00
8	(REAR) TO SPRAY PAINTING	New	1,000.00	800.00
9	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS	New	1,000.00	800.00
10	TO REMOVE AND REFIT INNER TRIM	New	150.00	60.00
			Gross Labour Cost (S\$)	2,780.00
				2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >