

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22006013/TPA3Q2**Date:** 24/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MPC0001970_01

Claimant Vehicle No : SLU3708U **Insured Vehicle No :** SJN4764K

Date of Loss: 22/06/2022 Nature of Claim: TP Claim No: MPC2022D0003418

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU3708U**
 Make & Model: AUDI A6, 2.0 TFSI MU (A) Engine No: CDN249361
 Reg. Date: 23/02/2012 (Man. Year: 2011) Chassis No: WAUZZZ4G5CN104495
 Colour: White Odometer: 130655 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 245/40 R19
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,662.25	6,333.44	6,328.81	49.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,350.00	1,410.00	51.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,422.25	7,683.44	7,738.81	50.18
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	15,422.25	6,100.00	9,322.25	60.45
+ GST 7.00/7.00% (S\$)	1,079.56	427.00	652.56	60.45
Nett Amount (S\$)	16,501.81	6,527.00	9,974.81	60.45
+ Car Rental (5.0 x S\$150.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,284.45		
Global Sum Settlement (S\$)		7,200.00		

INSPECTION

Date of Assignment: 23/06/2022

Date Inspected: 24/06/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2022)
Parts:	143	AUDI A6 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU3708U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID (ALUMINIUM)	Bent	3,789.00 FL	*2,300.00 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	138.00 FL	*100.00 FL
3	1		*BOOTLID A6 EMBLEM	Necessary	103.00 FL	*87.00 FL
4	1		*BOOTLID 2.0T EMBLEM	Necessary	98.00 FL	*98.00 FL
5	1		*BOOTLID LOCK	Not Necessary	278.00 FL	*- FL
6	1		*BOOTLID LOCK CATCH	Not Necessary	152.00 FL	*- FL
7	1		*REAR BUMPER	Deformed	2,519.00 FL	*2,058.54 FL
8	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
9	1		*REAR BUMPER LOWER SPOILER	Cut	453.00 FL	*282.84 FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	872.00 FL	*774.40 FL
11	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Necessary	228.00 FL	*- FL
12	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Not Working	228.00 FL	*185.00 FL
13	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Not Working	228.00 FL	*185.00 FL
14	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Not Necessary	228.00 FL	*- FL
15	4		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	102.00 FL	*102.00 FL
16	4		*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	128.00 FL	*128.00 FL
17	1		*REAR BUMPER TOWING COVER	Not Necessary	78.00 FL	*- FL
18	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	45.00 FL	*- FL
19	1		*REAR BUMPER RH LOWER BRACKET	Cut	22.00 FL	*22.00 FL
20	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	45.00 FL	*- FL
21	1		*REAR BUMPER LH LOWER BRACKET	Cracked	22.00 FL	*22.00 FL
22	1		*REAR BUMPER CENTRE BRACKET	Cracked	292.00 FL	*292.00 FL
23	1		*END PANEL	Repair	556.00 FL	*- FL
24	1		*END PANEL INNER GARNISH	Not Necessary	189.00 FL	*- FL
25	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
26	1		*RH TAILLAMP ASSY	Not Necessary	1,181.00 FL	*- FL
27	1		*LH TAILLAMP ASSY	Not Necessary	1,181.00 FL	*- FL
28	1		*END PANEL JOINT SEALANT	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,325.00	6,666.78
- List Item Discount on L Items 5.00/5.00% (\$\$)	662.75	333.34
Total Parts (\$\$)	12,662.25	6,333.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	50.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	60.00	30.00
5	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO NEW BOOTLID	New	180.00	0.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	120.00	30.00
7	REMOVE AND REPLACE REAR INNER GARNISH AND TRIMS TO ASSIST REPAIR	New	350.00	60.00
Gross Labour Cost (S\$)			2,760.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >