

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22006019/RNY3Q2**Date:** 03/10/2022**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000708504
Claimant Vehicle No :	SMP9373B	Insured Vehicle No :	YP7000Z
Date of Loss:	21/06/2022	Nature of Claim:	TP
		Claim No:	202222005347KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP9373B	Engine No:	A25A5433142
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	JTNBA3HK801064905
Reg. Date:	23/04/2021 (Man. Year: 2020)	Odometer:	20204 km
Colour:	Black		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,963.60	12,468.70	18,494.90	59.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	2,670.00	510.00	16.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,143.60	15,138.70	19,004.90	55.66
+ GST 7.00/7.00% (S\$)	2,390.05	1,059.71	1,330.34	55.66
Nett Amount (S\$)	36,533.65	16,198.41	20,335.24	55.66

INSPECTION

Date of Assignment:	23/06/2022		
Date Inspected:	24/06/2022	Inspected At:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18 Singapore 757700
Estimated Period of Repair:	12.0 days		

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$15,138.69

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2022)
Parts: 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMP9373B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	685.10 F	*625.00 FL
2	10		*BUMPER CLIPS	Necessary	55.00 F	*55.00 FL
3	1		*FRONT BUMPER RETAINER RH	Serviceable	91.60 F	*- FL
4	1		*FRONT BUMPER RETAINER LH	Serviceable	91.60 F	*- FL
5	1		*FRONT BUMPER PAD RH	Not Necessary	68.10 F	*- FL
6	1		*FRONT BUMPER PAD LH	Not Necessary	38.10 F	*- FL
7	1		*FRONT BUMPER SIDE MOULDING RH	Scratched	102.30 F	*102.30 FL
8	1		*FRONT BUMPER TOP RUBBER SEAL	Necessary	70.30 F	*70.30 FL
9	1		*FRONT REINFORCEMENT	Bent	480.70 F	*387.00 FL
10	1		*FRONT SPONGE	Cracked	127.80 F	*127.80 FL
11	1		*FRONT GRILLE ASSY	Cracked	691.90 F	*653.60 FL
12	1		*FRONT BUMPER LOWER GRILLE	Cracked	411.80 F	*411.80 FL
13	10		*FRONT GRILLE CLIPS	Necessary	75.00 F	*50.00 FL
14	1		*FRONT EMBLEM	Scratched	1,091.40 F	*1,091.40 FL
15	1		*HEAD LAMP RH	Cracked	2,855.70 F	*2,721.10 FL
16	1		*RADIATOR UPPER AIR GUIDE	Scratched	212.00 F	*212.00 FL
17	1		*RADIATOR AIR GUIDE RH	Deformed	104.60 F	*104.60 FL
18	1		*AIR FILTER HOSE	Serviceable	186.90 F	*- FL
19	1		*AIR INTAKE DUCT ASSY	Cracked	222.80 F	*222.80 FL
20	1		*SUPPORT PANEL ASSY	Bent	1,124.60 F	*1,124.60 FL
21	1		*A/C CONDENSER	Bent	2,125.00 F	*2,125.00 FL
22	1		*A/C PIPE DISCHARGE HOSE	Serviceable	696.50 F	*- FL
23	1		*A/C OUTLET PIPE	Serviceable	756.10 F	*- FL
24	1		*A/C COMPRESSOR SUCTION HOSE	Serviceable	791.60 F	*- FL
25	1		*RADIATOR	Serviceable	2,423.20 F	*- FL
26	1		*RADIATOR FAN ASSY	Serviceable	4,382.00 F	*- FL
27	1		*RADIATOR UPPER HOSE	Serviceable	64.40 F	*- FL
28	1		*RADIATOR LOWER HOSE	Serviceable	58.30 F	*- FL
29	1		*BONNET	Buckled	3,139.10 F	*1,766.00 FL
30	1		*BONNET HINGE RH	Serviceable	62.30 F	*- FL
31	1		*BONNET HINGE LH	Serviceable	62.30 F	*- FL
32	1		*BONNET LOCK	Bent	178.60 F	*178.60 FL
33	1		*BONNET RUBBER SEAL ASSY	Necessary	70.30 F	*70.30 FL
34	1		*INSULATOR	Deformed	633.30 F	*633.30 FL
35	10		*INSULATOR CLIPS	Necessary	90.00 F	*60.00 FL
36	1		*REAR BUMPER	Deformed	695.80 F	*695.80 FL
37	1		*REAR BUMPER UPPER RETAINER RH	Serviceable	117.90 F	*- FL
38	1		*REAR BUMPER UPPER RETAINER LH	Serviceable	117.90 F	*- FL
39	1		*REAR BUMPER LOWER RETAINER RH	Serviceable	46.00 F	*- FL
40	1		*REAR BUMPER LOWER RETAINER LH	Serviceable	46.00 F	*- FL
41	1		*REAR BUMPER REFLECTOR RH	Serviceable	63.40 F	*- FL
42	1		*REAR BUMPER REFLECTOR LH	Serviceable	63.40 F	*- FL
43	1		*REAR BUMPER LOWER MOULDING RH	Serviceable	102.30 F	*- FL
44	1		*REAR BUMPER LOWER MOULDING LH	Serviceable	102.30 F	*- FL
45	1		*REAR BUMPER SIDE GARNISH RH	Serviceable	60.10 F	*- FL
46	1		*REAR BUMPER SIDE GARNISH LH	Serviceable	60.10 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR CAMRY EMBLEM	Not Necessary	72.30 F	*- FL
48	1		*REAR HYBRID EMBLEM	Necessary	69.70 F	*69.70 FL
49	1		*BOOTLID	Bent	1,213.00 F	*1,213.00 FL
50	1		*BOOTLID HINGE RH	Serviceable	190.00 F	*- FL
51	1		*BOOTLID HINGE LH	Serviceable	190.00 F	*- FL
52	1		*BOOTLID HINGE COVER RH	Serviceable	95.60 F	*- FL
53	1		*BOOTLID HINGE COVER LH	Serviceable	95.60 F	*- FL
54	1		*BOOTLID LOCK	Serviceable	528.90 F	*- FL
55	1		*BOOTLID STRIKER	Serviceable	35.60 F	*- FL
56	1		*END PANEL TOP GARNISH	Deformed	314.20 F	*314.20 FL
57	1		*END PANEL ASSY	Bent	689.70 F	*689.70 FL
58	1		*REAR ANTENNA	Serviceable	76.30 F	*- FL
59	1		*FRONT PARKING SENSOR	Serviceable	300.00 FS	*- FS
60	1		*REAR PARKING SENSOR	Serviceable	300.00 FS	*- FS
61	1		*SEALANT (BONNET,BOOTLID & END PANEL)	Necessary	120.00 FS	*60.00 FS
62	1		*COOLANT FLUID 4 LITRES	Necessary	40.00 FS	*40.00 FS
63	1		*FRONT LICENSE PLATE CASING	Serviceable	20.00 FS	*- FS
64	1		*TAIL LAMP SIDE COVER RH	Cut	75.60 F	*75.60 FL
65	1		*REAR REINFORCEMENT	Bent	520.70 F	*420.20 FL
66	1		*RADIATOR TOP COVER	Cut	220.90 F	*220.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,963.60	16,591.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	4,122.90
Total Parts (\$\$)	30,963.60	12,468.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT (FRONT BUMPER ,BONNET ,REAR BUMPER ,BOOTLID & INNER PANELS)	New	1,250.00	1,200.00
2	REMOVE ,REPLACE AND REPAIR ACCIDENT AFFECTED AREA	New	1,200.00	1,200.00
3	REPAIR ,PANEL BEATING & RE-ALIGNING (SPARE TYRE SLINK)	New	350.00	0.00
4	REMOVE ,REFIT A/C ,RADIATOR & REFILL A/C GAS TO FACILITATE REPAIR	New	100.00	80.00
5	TRANSFER BOOTLID FITTING & MECHANISM TO BOOTLID	New	80.00	60.00
6	CHECK ,DIAGNOSE ,RECTIFY FAULT CODES & SENSOR CALIBRATION	New	150.00	100.00
7	CHECK AND RECTIFY ELECTRICAL WIRING	New	50.00	30.00
			Gross Labour Cost (\$\$)	3,180.00
				2,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >