

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006021/APA3Q2**Date:** 26/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800151753
Claimant Vehicle No :	SMW9670G	Insured Vehicle No :	ET4A
Date of Loss:	21/06/2022	Nature of Claim:	TP
		Claim No:	9003380059SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW9670G		
Make & Model:	HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A)	Engine No:	G4FMLU191848
Reg. Date:	21/12/2020 (Man. Year: 2020)	Chassis No:	KMHLN41ETMU093486
Colour:	Blue	Odometer:	29982 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,365.36	4,703.76	3,661.60	43.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,690.00	620.00	26.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,675.36	6,393.76	4,281.60	40.11
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	10,675.36	5,100.00	5,575.36	52.23
+ GST 7.00/7.00% (S\$)	747.28	357.00	390.28	52.23
Nett Amount (S\$)	11,422.64	5,457.00	5,965.64	52.23
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		6,157.00		

INSPECTION

Date of Assignment:	23/06/2022		
Date Inspected:	23/06/2022	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,023.00 FL	*1,782.00 FL
2	1		*H EMBLEM	Necessary	47.00 FL	*47.00 FL
3	1		*AVANTE EMBLEM	Necessary	56.00 FL	*56.00 FL
4	1		*S EMBLEM	Necessary	36.00 FL	*36.00 FL
5	2		*BOOTLID REFLECTOR	Cracked	1,470.00 FL	*1,328.00 FL
6	1		*BOOTLID LOCK	Damaged	119.00 FL	*119.00 FL
7	1		*BOOTLID W/STRIP	Not Necessary	118.00 FL	*- FL
8	1		*BOOTLID OUTER GARNISH	Not Necessary	856.00 FL	*- FL
9	1		*REAR BUMPER	Deformed	679.80 FL	*495.00 FL
10	2		*REAR BUMPER RETAINER	Necessary	58.00 FL	*58.00 FL
11	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	756.00 FL	*378.00 FL
12	1		*REAR BUMPER LOWER LIP	Cut	340.00 FL	*340.00 FL
13	1		*REAR BUMPER REFLECTOR	N/S Cracked	118.40 FL	*59.20 FL
14	1		*REAR BUMPER THIRD BRAKE LIGHT	Cracked	201.50 FL	*201.50 FL
15	1		*REAR BUMPER REINFORCEMENT	Damaged	299.00 FL	*299.00 FL
16	2		*REAR NO PLATE LAMP	Cracked	64.00 FL	*64.00 FL
17	2		*TAILLAMP	Not Necessary	1,752.00 FL	*- FL
18	4		*REAR BUMPER BRACKET	Damaged	280.00 FL	*100.00 FL
19	2		*REAR BUMPER CLIPS	Necessary	11.00 FL	*11.00 FL
20	1		*END PANEL	Dented	654.00 FL	*456.00 FL
21	1		*END PANEL INNER GARNISH	Not Necessary	169.00 FL	*- FL
22	1		*SPARE TYRE CARDBOARD	Not Necessary	299.00 FL	*- FL
23	1		*REAR NO PLATE	Dented	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,446.70	5,869.70
- List Item Discount on L Items 20.00/20.00% (S\$)	2,081.34	1,165.94
Total Parts (S\$)	8,365.36	4,703.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	30.00	30.00
4	RUST PROOFING	New	80.00	60.00
Gross Labour Cost (\$\$)			2,310.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >