

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006023/AQCE2**Date:** 30/11/2022**REFERENCE**

Insured/Claimant:	TAN SIK CHYE	Policy No:	2100501630-05	Claim No:	4249941899SG
Date of Loss:	13/06/2022	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL5271X	Engine No:	CYG017811
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Chassis No:	WAUZZZ4G5HN064989
Reg. Date:	28/02/2017 (Man. Year: 2016)	Odometer:	128806 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$102,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,460.00	14,804.24	13,655.76	47.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,752.00	13,337.00	8,415.00	38.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,212.00	28,141.24	22,070.76	43.96
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	49,412.00	27,341.24	22,070.76	44.67
+ GST 7.00/7.00% (S\$)	3,458.84	1,913.89	1,544.95	44.67
Nett Amount (S\$)	52,870.84	29,255.13	23,615.71	44.67

INSPECTION

Date of Assignment:	24/06/2022		
Date Inspected:	23/06/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	15.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	3,475.00 FS	*- FS
2	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	60.00 FS	*- FS
3	1		*REAR FENDER-LH	Dented	4,870.00 FS	*3,896.00 FS
4	1		*REAR WINDSCREEN	Necessary	1,307.00 FS	*1,045.60 FS
5	1		*QUARTER WINDOW-LH	Necessary	434.00 FS	*346.80 FS
6	2		*PRIMER	Necessary	44.00 FS	*34.72 FS
7	1		*REAR SILL TRIM STRIP-LH	Necessary	133.00 FS	*106.00 FS
8	1		*SIDE MEMBER TRIM-LH	Not Necessary	905.00 FS	*- FS
9	1		*SILL PANEL CLIP ATTACHMENT PARTS	Necessary	93.00 FS	*74.24 FS
10	1		*SILL PANEL ADHESIVE TAPES	Necessary	18.00 FS	*14.24 FS
11	1		*REAR BUMPER STONE CHIP GUARD-LH	Not Necessary	133.00 FS	*- FS
12	1		*REAR WHEEL HOUSING LINER-LH	Not Necessary	299.00 FS	*- FS
13	1		*REAR DOOR-LH	Dented	4,760.00 FS	*3,808.00 FS
14	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
15	1		*REAR DOOR OUTER SEAL-LH	Necessary	256.00 FS	*204.80 FS
16	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
17	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
18	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
19	1		*REAR DOOR SEAL OUTER-LH	Not Necessary	322.00 FS	*- FS
20	1		*REAR DOOR CATCH-LH	Not Necessary	134.00 FS	*- FS
21	1		*FRONT DOOR-LH	Dented	4,760.00 FS	*3,808.00 FS
22	1		*FRONT DOOR STONE GUARD FILM-LH	Necessary	135.00 FS	*108.00 FS
23	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	199.00 FS	*- FS
24	1		*FRONT DOOR OUTER SEAL-LH	Necessary	256.00 FS	*204.80 FS
25	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
26	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
27	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
28	1		*FRONT DOOR CATCH-LH (NPA)	Not Necessary	0.00 FS	*- FS
29	1		*WING MIRROR MOUNTING-LH	Not Necessary	1,552.00 FS	*- FS
30	1		*WING MIRROR HOUSING-LH	Repair	221.00 FS	*- FS
31	1		*TURN SIGNAL INDICATOR	Not Necessary	141.00 FS	*- FS
32	1		*WING MIRROR GLASS-LH	Not Necessary	1,298.00 FS	*- FS
33	1		*FRONT DOOR HANDLE, EXTERIOR-LH	Repair	651.00 FS	*- FS
34	1		*FRONT DOOR CAP-PASSENGER DOOR	Repair	129.00 FS	*- FS
35	1		*ARYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
36	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
37	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
38	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
39	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
41	1		*SUNDRIES	Necessary	400.00 FS	*40.64 FS
42	1		*CLIP SET FOR CHROME TRIM (Supplementary)	Necessary	41.00 FS	*32.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **28,460.00** **14,804.24**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	600.00	600.00
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN AND 1/4 GLASS	New	200.00	150.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	400.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS.BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,CD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	800.00	560.00
8	TO DISMANTLE AND RENEW REAR BUMPER,LHS REAR DOOR,LHS FRONT DOOR AND LHS SILL PANEL TRIM.TO CUT OUT AND WELD LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	8,000.00	4,000.00
9	TO RESPRAY REAR BUMPER,LHS REAR FENDERS,LHS REAR DOOR,LHS FRONT DOOR,LHS WING MIRROR COVER,DOOR HANDLE,LHS SILL PANEL TRIM,LHS SILL PANEL,ROOF CHANNEL,DRAIN CHANNEL,DOOR ENTRANCE AND REAR END PANELLING	New	8,000.00	3,875.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			21,752.00	13,337.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >