

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/HLA22006024/UQY3M4**Date:** 08/07/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP306811
<b>Claimant Vehicle No :</b>	GBC6565H	<b>Insured Vehicle No :</b>	SKS1088K
Date of Loss:	17/06/2022	Nature of Claim:	TP
		Claim No:	MPC03507/GN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBC6565H</b>	Engine No:	1KD2294297
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P500115351
Reg. Date:	28/05/2013 (Man. Year: 2013)	Odometer:	204104 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,551.80	1,762.12	5,789.68	76.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,870.00	830.00	30.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,251.80</b>	<b>3,632.12</b>	<b>6,619.68</b>	<b>64.57</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,900.00</b>		
<b>Nett Amount (\$\$)</b>	<b>10,251.80</b>	<b>2,900.00</b>	<b>7,351.80</b>	<b>71.71</b>

INSPECTION

Date of Assignment:	24/06/2022	LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883
Date Inspected:	24/06/2022 Inspected At:	
Estimated Period of Repair:	6.0 days	

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 07 Jul 2022)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBC6565H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL HUB-CAB (CRACKED)	Not Consistent With The Impact	278.00 F	*- FL
2	1		*REAR BUMPER (DENTED)	Not Consistent With The Impact	599.30 F	*- FL
3	1		*REAR RH FENDER (BODY PANEL) (DENTED)	Not Consistent With The Impact	1,718.50 F	*- FL
4	1		*REAR RH WHEEL HUB-CAB (CRACKED)	Not Consistent With The Impact	278.00 F	*- FL
5	1		*REAR LH BUMPER BRACKET	Not Necessary	202.00 F	*- FL
6	1		*FRONT LH SIDE PANEL	Badly Dented	477.00 F	*477.00 FL
7	1		*FRONT LH SLIDING DOOR	Badly Dented	1,594.50 F	*1,594.50 FL
8	1		*REAR LH FENDER (BODY PANEL)	Repair	1,718.50 F	*- FL
9	1		*REAR LH WHEEL RIM	Repair	360.00 F	*- FL
10	1		*REAR LH WHEEL HUB-CAB	Cut	278.00 F	*278.00 FL
11	1		*SET REAR BUMPER CLIPS	Not Necessary	48.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,551.80</b>	<b>2,349.50</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	587.38

<b>Total Parts (\$\$)</b>	<b>7,551.80</b>	<b>1,762.12</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	1,000.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,200.00	750.00
3	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	180.00	60.00
4	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	120.00	60.00
<b>Gross Labour Cost (\$)</b>			<b>2,700.00</b>	<b>1,870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >