

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006028/TQY3Q2**Date:** 05/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00020072100

**Claimant Vehicle
No :** SJA9397Y**Insured
Vehicle No :** SKR2014Y

Date of Loss: 23/06/2022

Nature of Claim: TP

Claim
No: SNM22D204392/C02/TANKW**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJA9397Y**

Make & Model: TOYOTA WISH, 1.8 X LIMITED (A)

Engine No: HIDDEN

Reg. Date: 01/12/2007 (Man. Year: 2007)

Chassis No: ZNE100371731

Colour: White

Odometer: 253627 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,616.12	5,390.82	8,225.30	60.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,340.00	2,010.00	3,330.00	62.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,956.12	7,400.82	11,555.30	60.96
Approved Total (Overridden) (\$\$)		5,900.00		
Nett Amount (\$\$)	18,956.12	5,900.00	13,056.12	68.88

INSPECTION

Date of Assignment: 24/06/2022

Date Inspected: 24/06/2022 Inspected At:

HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 X LIMITED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA9397Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	590.00 FL	*590.00 FL
2	1		*REAR BUMPER REFLECTOR	N/S Cracked / O/SNot Necessary	136.00 FL	*68.00 FL
3	1		*REAR BUMPER BRACKET	N/S Cracked / O/SNot Necessary	140.20 FL	*70.10 FL
4	1		*REAR BUMPER SIDE RETAINER	N/S Cracked / O/SNot Necessary	120.00 FL	*60.00 FL
5	1		*TAILLAMP C/W BRACKET	N/S Cracked / O/SNot Necessary	1,040.00 FL	*417.00 FL
6	1		*TAIL LAMP PANEL LH (OUTER) }	N/S Cracked / O/SNot Necessary	487.00 FL	*297.00 FL
7	1		*TAIL LAMP PANEL LH (INNER) }	Bent	496.00 FL	*- FL
8	1		*REAR FENDER LH	Buckled	980.00 FL	*980.00 FL
9	1		*REAR FENDER INNER PANEL LH	Repair	683.00 FL	*- FL
10	1		*REAR FENDER INNER TRIM LH	N/SDeformed / O/SNot Necessary	1,476.20 FL	*600.00 FL
11	1		*REAR FENDER QUARTER GLASS C/W MOULDING LH	Not Necessary	580.00 FL	*- FL
12	1		*REAR FENDER INNER COWLING	N/S Torn / O/S Not Necessary	760.00 FL	*290.00 FL
13	1		*REAR FENDER INNER BOTTOM PANEL LH	Repair	455.00 FL	*- FL
14	1		*REAR FENDER AIR VENT	Deformed	95.00 FL	*95.00 FL
15	1		*TAILGATE	Bent	1,280.00 FL	*1,201.00 FL
16	1		*TAILGATE OUTER MOULDING	Not Necessary	240.00 FL	*- FL
17	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
18	1		*TAILGATE INNER LOCK	Not Necessary	445.10 FL	*- FL
19	1		*TAILGATE LOWER LOCK	Not Necessary	35.00 FL	*- FL
20	2		*TAILGATE DAMPER	Not Necessary	388.00 FL	*- FL
21	2		*TAILGATE STOPPER	Not Necessary	40.00 FL	*- FL
22	1		*TAILGATE WEATHER STRIP	Cut	320.00 FL	*288.00 FL
23	1		*TAILGATE INNER TRIM (LOWER)	Cracked	395.00 FL	*328.00 FL
24	1		*TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
25	1		*REAR FLOOR TOP BOARD	Deformed	425.00 FL	*322.00 FL
26	1		*REAR FLOOR TOP BOARD INNER SUPPORT	Not Necessary	410.00 FL	*- FL
27	1		*REAR FLOOR TOP SIDE BOARD LH	Deformed	125.00 FL	*125.00 FL
28	1		*REAR END PANEL	Bent	480.00 FL	*480.00 FL
29	1		*REAR END PANEL TOP GARNISH	Deformed	245.00 FL	*245.00 FL
30	1		*REAR END PANEL (EXTEND) RH	Not Necessary	295.00 FL	*- FL
31	1		*REAR JACK HOLDER PANEL	Not Necessary	185.00 FL	*- FL
32	1		*REAR CHASSIS MEMBER LH	Not Necessary	1,450.00 FL	*- FL
33	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
34	1		*REAR BUMPER STICKER	Necessary	180.00 FS	*50.00 FS
35	3		*TAILGATE STICKER	Necessary	300.00 FS	*150.00 FS
36	1		*SET TAILGATE OUTER MOULDING CLIP	Not Necessary	60.00 FS	*- FS
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
38	1		*TAILGATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
39	1		*TAILGATE SIDE LINING	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

10/5/22, 4:26 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SET TAILLAMP CLIP	Necessary	50.00 FS	*10.00 FS
41	1		*REAR FENDER SEALANT LH	Necessary	150.00 FS	*50.00 FS
42	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
43	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
44	1		*REAR QUARTER GLASS SEALANT LH	Necessary	80.00 FS	*40.00 FS
45	1		*REAR QUARTER GLASS INNER SHIELD LH	Not Necessary	60.00 FS	*- FS
46	1		*REAR QUARTER GLASS SOLAR FILM LH	Not Necessary	350.00 FS	*- FS
47	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*40.00 FS
48	1		*REAR END PANEL TOP GARNISH	Not Necessary	60.00 FS	*- FS
49	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,361.50	7,051.10
- List Item Discount on L Items 25.00/25.00% (\$\$)					3,745.38	1,660.28
Total Parts (\$\$)					13,616.12	5,390.82
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TUFF COAT	New	250.00	30.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
6	CONDUCT WATER LEAKAGE TEST	New	120.00	30.00
7	REMOVE AND REFIX REAR FENDER GLASS LH	New	80.00	50.00
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	30.00
9	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	REMOVE AND REFIX FUEL TANK	New	120.00	0.00
12	REAR CHASSIS ALIGNMENT	New	180.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,340.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >