

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006029/EQCE2**Date:** 22/11/2022**REFERENCE**

Insured/Claimant: WANG TAO Policy No: 7220057330
Date of Loss: 22/06/2022 Nature of Claim: OD Claim No: 5833981110SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW1306Z**
Make & Model: AUDI A5, 2.0 SPORTBACK (A) Engine No: DEM034245
Reg. Date: 28/05/2022 (Man. Year: 2021) Chassis No: WAUZZZF56MA062407
Colour: Blue Odometer: 1073 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$240,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Hankook 5 mm Rear Left Side: Hankook 5 mm
Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 34,254.40 | 13,931.36 | 20,323.04 | 59.33 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 28,722.00 | 13,987.00 | 14,735.00 | 51.30 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 62,976.40 | 27,918.36 | 35,058.04 | 55.67 |
| + GST 7.00/7.00% (S\$) | 4,408.35 | 1,954.29 | 2,454.06 | 55.67 |
| Nett Amount (S\$) | 67,384.75 | 29,872.65 | 37,512.10 | 55.67 |

INSPECTION

Date of Assignment: 24/06/2022
Date Inspected: 23/06/2022 Inspected At: 24 Benoi Sector Singapore 629857
Estimated Period of Repair: 16.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|---------------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Dented | 2,609.00 FS | *2,087.20 FS |
| 2 | 2 | | *REAR BUMPER GUIDE SECTION - LH / RH | Not Necessary | 75.00 FS | *- FS |
| 3 | 1 | | *TAIL LIGHT OUTER - RH | Not Necessary | 1,269.00 FS | *- FS |
| 4 | 1 | | *REAR FENDER - RH | Dented | 4,076.00 FS | *3,260.80 FS |
| 5 | 1 | | *QUARTER WINDOW - RH | Necessary | 798.00 FS | *638.00 FS |
| 6 | 1 | | *PRIMER | Necessary | 22.00 FS | *17.36 FS |
| 7 | 1 | | *FUEL INSERT | Necessary | 100.00 FS | *79.28 FS |
| 8 | 1 | | *FUEL FILLER FLAP | Cut | 343.00 FS | *274.00 FS |
| 9 | 1 | | *REAR FENDER WHEEL HOUSING - RH OUTER | Dented | 715.00 FS | *571.60 FS |
| 10 | 1 | | *REAR FENDER INENR - RH | Not Necessary | 1,332.00 FS | *- FS |
| 11 | 1 | | *REAR VENT TRIM | Not Necessary | 75.00 FS | *- FS |
| 12 | 1 | | *BOTTOM PLATE - RH OUTER | Not Necessary | 506.00 FS | *- FS |
| 13 | 1 | | *ACTIVATED CHARCOAL CONTAINER | Not Necessary | 647.00 FS | *- FS |
| 14 | 1 | | *ACTIVATED CHARCOAL CONTAINER BRACKET | Not Necessary | 123.00 FS | *- FS |
| 15 | 1 | | *REAR DOOR - RH | Dented | 3,977.00 FS | *3,181.60 FS |
| 16 | 1 | | *REAR DOOR OUTER SEAL - RH | Necessary | 247.00 FS | *197.20 FS |
| 17 | 1 | | *BONDING AGENT | Not Necessary | 51.00 FS | *- FS |
| 18 | 1 | | *CLEANING SOLUTION | Not Necessary | 74.00 FS | *- FS |
| 19 | 1 | | *APPLICATOR | Not Necessary | 8.00 FS | *- FS |
| 20 | 1 | | *REAR DOOR ATTACHMENT PARTS | Not Necessary | 180.00 FS | *- FS |
| 21 | 1 | | *REAR DOOR CATCH - RH | Not Necessary | 134.00 FS | *- FS |
| 22 | 1 | | *REAR DOOR HANDLE TRIM PLATE - RH | Not Necessary | 98.00 FS | *- FS |
| 23 | 1 | | *REAR DOOR HANDLE COVER - RH | Not Necessary | 7.00 FS | *- FS |
| 24 | 1 | | *REAR DOOR HANDLE HOUSING - RH | Not Necessary | 9.00 FS | *- FS |
| 25 | 1 | | *REAR DOOR HANDLE SENSOR - RH | Not Necessary | 255.00 FS | *- FS |
| 26 | 1 | | *REAR DOOR HANDLE, EXTERIOR - RH | Not Necessary | 47.00 FS | *- FS |
| 27 | 1 | | *REAR DOOR HANDLE MOUNTING BAR - RH | Not Necessary | 183.00 FS | *- FS |
| 28 | 1 | | *REAR DOOR LOCK - RH | Not Necessary | 630.00 FS | *- FS |
| 29 | 1 | | *REAR DOOR HANDLE STRIKER | Not Necessary | 111.00 FS | *- FS |
| 30 | 1 | | *REAR DOOR HANDLE UNDERLAY STRIKER | Not Necessary | 38.00 FS | *- FS |
| 31 | 1 | | *ROOF MOLDING CHROME - RH | Bent | 706.00 FS | *564.80 FS |
| 32 | 1 | | *REAR DOOR EDGE PROTECTOON RH | Not Necessary | 172.00 FS | *- FS |
| 33 | 1 | | *REAR DOOR WINDOW - RH | Not Necessary | 322.00 FS | *- FS |
| 34 | 1 | | *REAR DOOR SEAL, INNER - RH | Not Necessary | 657.00 FS | *- FS |
| 35 | 1 | | *AUDI RING EMBLEM STICKER | Necessary | 58.40 FS | *58.40 FS |
| 36 | 1 | | *SILL PANEL ATTACHMENT PARTS | Necessary | 136.00 FS | *108.80 FS |
| 37 | 1 | | *SILL PANEL ADHESIVE TAPES | Necessary | 221.00 FS | *176.80 FS |
| 38 | 1 | | *REAR WHEEL HOUSING LINER - RH | Crushed | 299.00 FS | *238.80 FS |
| 39 | 1 | | *REAR ALUMINIUM RIM | Cut | 1,889.00 FS | *1,511.20 FS |
| 40 | 1 | | *RUBBER VALVE (4PCS) | Necessary(1Pc Only) | 15.00 FS | *2.96 FS |
| 41 | 1 | | *SUSPENSION SUPPORT FRAME | Not Necessary | 3,643.00 FS | *- FS |
| 42 | 1 | | *WISHBONE ALUMINIUM - LOWER | Not Necessary | 963.00 FS | *- FS |
| 43 | 1 | | *WISHBONE - RH UPPER | Not Necessary | 624.00 FS | *- FS |
| 44 | 1 | | *WISHBONE - RH FRONT | Not Necessary | 137.00 FS | *- FS |
| 45 | 1 | | *WISHBONE - RH REAR | Not Necessary | 501.00 FS | *- FS |
| 46 | 1 | | *TRACK ROD - RH | Not Necessary | 188.00 FS | *- FS |
| 47 | 1 | | *WHEEL BEARING HOUSING - RH | Not Necessary | 1,097.00 FS | *- FS |
| 48 | 1 | | *WHEELHUB BEARING | Not Necessary | 723.00 FS | *- FS |
| 49 | 1 | | *WHEEL BEARING STONE CHIP GUARD - RH | Not Necessary | 49.00 FS | *- FS |
| 50 | 1 | | *GAS SHOCK ABSORBER | Not Necessary | 342.00 FS | *- FS |
| 51 | 1 | | *COUPLING ROD | Not Necessary | 94.00 FS | *- FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|---------------|------------|------------|
| 52 | 1 | | *ANTI-ROLL BAR | Not Necessary | 456.00 FS | *- FS |
| 53 | 1 | | *LEVEL SENSOR - RH | Not Necessary | 363.00 FS | *- FS |
| 54 | 1 | | *REAR PARKING AID SENSOR - SIDE | Not Necessary | 265.00 FS | *- FS |
| 55 | 6 | | *REAR PARKING AID SENSOR SEAL RING | Not Necessary | 15.00 FS | *- FS |
| 56 | 1 | | *ACRYLIC SEALANT | Necessary | 180.00 FS | *180.00 FS |
| 57 | 1 | | *CAVITY WAX | Necessary | 140.00 FS | *140.00 FS |
| 58 | 1 | | *STONE CHIP | Necessary | 180.00 FS | *180.00 FS |
| 59 | 1 | | *METAL FILLER POWDER | Necessary | 280.00 FS | *280.00 FS |
| 60 | 1 | | *1/4 GLASS SEALANT | Necessary | 100.00 FS | *100.00 FS |
| 61 | 1 | | *RHS REAR TYRE (NPA) | Not Necessary | 0.00 FS | *- FS |
| 62 | 1 | | *SUNDRIES | Necessary | 700.00 FS | *82.56 FS |

F=Franchise part. S=SpcNett.

| | | |
|---------------------------|------------------|------------------|
| Total Parts (\$\$) | 34,254.40 | 13,931.36 |
|---------------------------|------------------|------------------|

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|------------------|------------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR | New | 360.00 | 360.00 |
| 2 | TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER | New | 300.00 | 300.00 |
| 3 | TO CARRY OUT WATER SEEPAGE FOR 1/4 GLASS | New | 200.00 | 150.00 |
| 4 | TO INSTALL SOLAR FILM FOR 1/4 GLASS AND RHS REAR DOOR WINDOW GLASS | New | 400.00 | 400.00 |
| 5 | TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY | New | 1,600.00 | 1,600.00 |
| 6 | TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES | New | 400.00 | 280.00 |
| 7 | TO RENEW RHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT | New | 520.00 | 280.00 |
| 8 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| 9 | TO REMOVE AND RENEW RHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME | New | 2,400.00 | 0.00 |
| 10 | TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO CUT OUT AND WELD RHS REAR FENDER, RHS REAR BOTTOM PLATE, RHS OUTER WHEEL HOUSING WITH CONENCTING PLATE AND RHS SIDE PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 11,000.00 | 4,500.00 |
| 11 | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN ETC | New | 1,600.00 | 1,600.00 |
| 12 | TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, RHS SILL PANEL TRIM, RHS OUTER WHEEL HOUSING, BOTTOM PLATE, RHS SIDE PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING | New | 9,000.00 | 3,575.00 |
| 13 | TO REMOVE AND RE-INSTALL FUEL TANK ASSY TO FACILITATE CUTTING OF REAR WHEEL HOUSE PANEL (Supplementary) | New | 600.00 | 600.00 |
| 14 | TO RE-APPLY PAINT COATING ON AFFECTED AREA (Supplementary) | New | 150.00 | 150.00 |
| Gross Labour Cost (S\$) | | | 28,722.00 | 13,987.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >