

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22006033/EQY3Q2**Date:** 14/09/2022REFERENCE

Insured/Claimant: TAN WEE TAR, WESLEY Policy No: DMPG21013795
Date of Loss: 22/06/2022 Nature of Claim: OD Claim No: CDMPG22001216

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE9385K**
Make & Model: SKODA OCTAVIA, 1.4 AMBITION PLUS TSI (A) Engine No: CZDA76056
Reg. Date: 06/04/2020 (Man. Year: 2019) Chassis No: TMBBC7NE6L0074234
Colour: Grey Odometer: 36584 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$99,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm
Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,843.93	10,321.01	1,522.92	12.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,380.00	7,100.00	3,280.00	31.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,223.93	17,421.01	4,802.92	21.61
+ GST 7.00/7.00% (S\$)	1,555.68	1,219.47	336.21	21.61
Nett Amount (S\$)	23,779.61	18,640.48	5,139.13	21.61

INSPECTION

Date of Assignment: 24/06/2022

Date Inspected: 28/06/2022 Inspected At:

NO 17 TUAS AVE 9 SINGAPORE 639197
Repairer:Skoda Centre Singapore (HQ)

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Sep 2022)**Parts:** 143 SKODA OCTAVIA 1.4 AMBITION PLUS TSI (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SJE9385K)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD FRT BONNET	Dented	1,768.46 FS	*1,768.46 FS
2	1		*SKODA EMBI	Necessary	68.57 FS	*68.57 FS
3	1		*COVER FOR FRT BUMPER	Broken	1,352.70 FS	*1,352.70 FS
4	1		*GUIDE PIEC BUMPER SIDE BRACKET RH	Not Necessary	46.22 FS	*- FS
5	1		*GUIDE PIEC BUMPER SIDE BRACKET LH	Not Necessary	46.22 FS	*- FS
6	1		*SUPPORT PA LHS RADIATOR GRILLE INNER BRACKET	Not Necessary	55.31 FS	*- FS
7	1		*SUPPORT PA RHS RADIATOR GRILLE INNER BRACKET	Not Necessary	55.31 FS	*- FS
8	1		*SENSOR BRACKET	Necessary	13.00 FS	*13.00 FS
9	1		*SENSOR BRACKET	Necessary	13.00 FS	*13.00 FS
10	1		*SENSOR BRACKET	Necessary	13.00 FS	*13.00 FS
11	1		*SENSOR BRACKET	Necessary	13.00 FS	*13.00 FS
12	1		*2K PLASTIC ADHESIVE	Necessary	85.94 FS	*85.94 FS
13	1		*BONDING AGENT FOR PLASTIC	Necessary	68.85 FS	*68.85 FS
14	1		*SENSOR PRIMED	Not Necessary	190.18 FS	*- FS
15	1		*SEAL RING SATIN BLACK	Necessary	1.46 FS	*1.46 FS
16	1		*UNBEKANNT RADIATOR GRILLE	Cut	253.64 FS	*253.64 FS
17	1		*STICKER OVERFILLED ENGINE	Necessary	16.43 FS	*16.43 FS
18	1		*STICKER OIL COMPLY WITH	Necessary	26.52 FS	*26.52 FS
19	1		*STICKER AC REFRIGERAN	Necessary	18.87 FS	*18.87 FS
20	1		*COVER STRI RADIATOR GRILLE CHROM	Cut	271.87 FS	*271.87 FS
21	1		*COOLING AI BUMPER CTR LOWER GRILLE	Cut	119.29 FS	*119.29 FS
22	1		*COVER FOR LHS FOG LAMP GRILLE	Cut	41.04 FS	*41.04 FS
23	1		*COVER FOR RHS FOG LAMP GRILLE	Cut	41.04 FS	*41.04 FS
24	1		*BUFFER REINFORCEMENT	Broken	59.44 FS	*59.44 FS
25	1		*REINFORCEM	Not Necessary	777.93 FS	*- FS
26	1		*UNBEKANNT LHS H/LAMP	Broken	2,189.09 FS	*2,189.09 FS
27	1		*UNBEKANNT RHS H/LAMP	Broken	2,189.08 FS	*2,189.08 FS
28	1		*HALOGEN FO LHS FOG LAMP	Not Necessary	351.74 FS	*- FS
29	1		*FRT NUMBER PLATE	Cut	80.00 FS	*80.00 FS
30	1		*LOCK CARRIER	Broken	761.79 FS	*761.79 FS
31	1		*SEAL RING	Necessary	7.08 FS	*7.08 FS
32	1		*SEAL RING	Necessary	7.67 FS	*7.67 FS
33	2		*COOLANT 1B	Necessary	45.90 FS	*45.90 FS
34	1		*A/C OIL	Necessary	39.22 FS	*39.22 FS
35	1		*RHS FENDER	Bent	749.79 FS	*749.78 FS
36	2		*RIVETTED CAP NUT	Necessary	5.28 FS	*5.28 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,843.93 10,321.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	3,360.00	3,360.00
2	SPRAY PAINT	New	3,200.00	2,400.00
3	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
5	TO ALIGN LED HEADLIGHT	New	100.00	100.00
6	SPRAY RHS FENDE	New	800.00	0.00
7	LABOUR TO REPLACED LOCK CARRIER	New	1,680.00	0.00
8	B&P LEAKED CHECK ,VACUUM & REGAS	New	420.00	420.00
9	A/C GAS	New	60.00	60.00
			Gross Labour Cost (\$)	7,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >