

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006034/KQY3Q2**Date:** 10/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00255892101		
Claimant Vehicle No :	SJJ3065Y	Insured Vehicle No :	SBQ707G		
Date of Loss:	21/06/2022	Nature of Claim:	TP	Claim No:	SNM22D204380/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ3065Y	Engine No:	R18A1792020
Make & Model:	HONDA STREAM, 1.8 X (A)	Chassis No:	RN61082892
Reg. Date:	08/09/2008 (Man. Year: 2008)	Odometer:	0 km
Colour:	Metallic Black	Engine Capacity:	1799 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Yes

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	LAUFENN 8 mm	Rear Left Side:	LAUFENN 8 mm
Front Right Side:	LAUFENN 8 mm	Rear Right Side:	LAUFENN 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,302.00	6,477.60	1,824.40	21.98
Miscellaneous Items	460.00	360.00	100.00	21.74
Labour	4,530.00	4,030.00	500.00	11.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,292.00	10,867.60	2,424.40	18.24
Approved Total (Overridden) (S\$)		10,850.00		
(S\$)	13,292.00	10,850.00	2,442.00	18.37
+ GST 7.00/7.00% (S\$)	930.44	759.50	170.94	18.37
Nett Amount (S\$)	14,222.44	11,609.50	2,612.94	18.37

INSPECTION

Date of Assignment:	24/06/2022 Present Location:	Cheng Hoe Motor Pte Ltd (Yishun) 38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05
Date Inspected:	24/06/2022 Inspected At:	SINGAPORE 757700 Repairer:Cheng Hoe Motor Pte Ltd (Yishun)
Estimated Period of Repair:	15.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts: M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJJ3065Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Bent	370.00 F	*370.00 FL
2	1		*1 PC REAR BUMPER TOW COVER	Missing	12.00 F	*12.00 FL
3	1		*6 PCS REASR BUMPER CLIP @2/PCE	Necessary	12.00 F	*12.00 FL
4	1		*1 PC TAILGATE	Bent	580.00 F	*580.00 FL
5	1		*1 PC TAILGATE EMBLEM - STREAM	Necessary	28.00 F	*28.00 FL
6	1		*1 PC TAILGATE OUTER GARNISH	Missing	150.00 F	*150.00 FL
7	1		*1 PC TAILGATE INNER LOCK	Dented	95.00 F	*95.00 FL
8	1		*1 PC TAILGATE INNER RUBBER	Distorted / Cut	100.00 F	*100.00 FL
9	1		*1 PC TAILGATE LOGO	Necessary	22.00 F	*22.00 FL
10	1		*1 PC TAILGATE INNER TRIM BOARD	Distorted	145.00 F	*145.00 FL
11	1		*1 PC REAR WINDSCREEN MOULDING	Necessary	65.00 F	*65.00 FL
12	1		*1 PC REAR END PANEL OUTER	Bent	240.00 F	*240.00 FL
13	1		*1 PC REAR END PANEL INNER TOP GARNISH	Buckled	105.00 F	*105.00 FL
14	1		*2 PCS TAILALMP @240/PCE	Cracked	480.00 F	*480.00 FL
15	1		*1 PC REAR SPARE TYRE COMPARTMENT	Bent	700.00 F	*700.00 FL
16	1		*1 PC REAR COMPARTMENT FRT TOOL BOX	Dented	90.00 F	*90.00 FL
17	1		*1 PC REAR SPARE TYRE TRAY	Bent	175.00 F	*175.00 FL
18	1		*1 PC FRT BUMPER	Buckled	360.00 F	*360.00 FL
19	1		*1 PC FRT BUMPER REINFORCEMENT	Bent	190.00 F	*190.00 FL
20	1		*1 PC FRT BUMPER SIDE RETAINER	Distorted	16.00 F	*16.00 FL
21	1		*1 PC FRT BUMPER SIDE RETAINER INNER	Distorted	38.00 F	*38.00 FL
22	1		*6 PCS FRT BUMPER CLIP @2/PCE	Necessary	12.00 F	*12.00 FL
23	1		*1 PC FRT GRILLE	Cracked	200.00 F	*200.00 FL
24	1		*1 PC FRT GRILLE TOP CHROME	Serviceable	205.00 F	*- FL
25	1		*1 PC FRT GRILLE LOGO	Necessary	18.00 F	*18.00 FL
26	1		*4 PCS FRT GRILLE CLIP @2/PCE	Necessary	8.00 F	*8.00 FL
27	1		*1 PC AIRCON CONDENSER	Punctured	530.00 F	*530.00 FL
28	1		*1 PC BONNET	Buckled	500.00 F	*500.00 FL
29	1		*2 PCS HEADLAMP HID \$500/PCE	Cracked	1,000.00 F	*1,000.00 FL
30	1		*D2 PCS HEADLAMP BRACKET @28/PCE	Cracked	56.00 F	*56.00 FL
Supplementary #1						
31	1		*1 PC RADIATOR	Punctured	890.00 F	*890.00 FL
32	1		*1 PC CTR EXHAUST PIPE	Bent	480.00 F	*480.00 FL
33	1		*1 PC REAR EXHAUST PIPE	Bent	430.00 F	*430.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,302.00	8,097.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,619.40
Total Parts (\$\$)	8,302.00	6,477.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT NO. PLATE (BENT)	35.00	35.00
2	1	1 PC REAR NO. PLATE (BENT)	35.00	35.00
3	1	1 ROLL REAR WINDSCREEN GUM (NECESSARY)	40.00	40.00
4	1	1 SET REVERSE CAMERA (SHORTED)	350.00	250.00
Sub Total (\$\$)			460.00	360.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	1) TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	2) TO PANEL BEATING ON REAR PORTION	New	1,600.00	1,400.00
3	3) TO PUTTY AND RESPRAY ON REAR COMPARTMENT, REAR END PANEL, REAR BOTH FENDERS, TAILGATE, REAR BUMPER AND ALL ACCIDENT AFFECTED AREAS	New	1,300.00	1,200.00
4	4) TO REMOVE AND REFIX REAR EXHAUST AND CHECK LEAKING	New	60.00	60.00
5	5) TO REMOVE AND REFIX REAR GARNISH, SEAT, CUSHION ETC	New	80.00	80.00
6	6) TO REMOVE AND REFIX AIRCON, CHECK AND REFILL GAS	New	100.00	100.00
7	7) TO REMOVE AND REFIX FRT BUMPER ASSY, GRILLE, HEADLAMPS, BONNET; KNOCK AND REPAIR FRT SUPPORT PANEL, FRT FENDER AND RE-ALIGN TO SAME	New	500.00	400.00
8	8) TO PUTTY AND RESPRAY ON FRT BUMPER, FRT BUMPER REINFORCEMENT, SUPPORT PANEL, BONNET, FENDERS AND ALL ACCIDENT AFFECTED AREAS	New	700.00	600.00
9	9) TO REMOVE AND REFIX CAMERA	New	30.00	30.00
10	10) TO RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			4,530.00	4,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >