

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006039/DQY3M4**Date:** 21/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00007012200

Claimant Vehicle No : SCE9896K **Insured Vehicle No :** CB6813K

Date of Loss: 19/06/2022 Nature of Claim: TP Claim No: SNM22D204424/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCE9896K**

Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27491031377940

Reg. Date: 09/07/2018 (Man. Year: 2018) Chassis No: WDD2050402R394482

Colour: Silver Odometer: 60389 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,922.30	4,924.49	1,997.81	28.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	1,020.00	600.00	37.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,542.30	5,944.49	2,597.81	30.41
Approved Total (Overridden) (S\$)		4,750.00		
Nett Amount (S\$)	8,542.30	4,750.00	3,792.30	44.39

INSPECTION

Date of Assignment: 18/07/2022

Date Inspected: 28/06/2022 Inspected At: Bethlehem Auto (HQ)
Blk 5035 Ang Mo Kio Industrial Park 2, #01-371
Singapore 569538

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2022)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCE9896K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP RH	Cut / Mounting Cracked	3,720.00 FL	*3,200.00 FL
2	1		*HEAD LAMP LOWER BRACKET RH	Broken	298.00 FL	*131.50 FL
3	1		*FRONT BUMPER	Cut	1,770.00 FL	*1,636.54 FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	229.00 FL	*- FL
5	1		*FRONT BUMPER SENSOR	1Pc Damaged/ 1Pc Not Necessary	626.00 FL	*209.78 FL
			(2PCS)			
6	1		*SET FRONT BUMPER SENSOR HOLDER	Serviceable	120.00 FL	*- FL
7	1		*FRONT BUMPER SIDE GARNISH RH	Not Necessary	101.35 FL	*- FL
8	1		*FRONT SUPPORT PANEL FRONT GARNISH	Broken	627.10 FL	*260.50 FL
9	1		*FRONT NO. PLATE & GARNISH	Not Necessary	90.00 FS	*- FS
10	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
11	1		*SET FRONT FENDER INNER SHIELD CLIPS	Serviceable	45.00 FS	*- FS
Sub Total (S\$)					7,671.45	5,468.32
- List Item Discount on L Items 10.00/10.00% (S\$)					749.15	543.83
Total Parts (S\$)					6,922.30	4,924.49

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	500.00	400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	500.00	400.00
3	TO RNR FRONT BUMPER SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
4	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	100.00	30.00
5	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	400.00	150.00
Gross Labour Cost (\$\$)			1,620.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >