

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR22006050/Eny3m4	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	19/07/2022	
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHF 283Z	Veh. Inspected	k	FBJ 3822Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/06/22/2031	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		24/06/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA JUPITER	c.c		134	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	MH355S004EK130851	Colour		RED	
	Odometer	75732 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	80/90-17	DUNLOP		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	90/80-17	DUNLOP		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS N/S BODY.	STAINED DAMAGES AT THE REAR N/S PORTION AND				
5.	General Information					
	Accident Date	09/06/2022	Inspect Date /	Time	27/06/2022 ( 01:27 PM )	
	Survey held at	RIGHT CLICK AUTOWORKS PT				
	7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b.	•	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		3 Work	ing Days	

Report Ref No. CS3/SMR22006050/Eny3m4

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

**Automotive Assessor** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser