

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22006057/DQY3E2
Date: 18/11/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 1001383182	
Claimant Vehicle No : SHB4146G	Insured Vehicle No : GBE7801J	
Date of Loss: 21/06/2022	Nature of Claim: TP	Claim No: 277402

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB4146G		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU397506
Reg. Date:	22/10/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU186765
Colour:	Blue	Odometer:	296166 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,246.64	11,528.96	16,717.68	59.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	1,630.00	4,220.00	72.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	34,096.64	13,158.96	20,937.68	61.41
Approved Total (Overridden) (\$\$)		10,500.00		
(\$\$)	34,096.64	10,500.00	23,596.64	69.21
+ GST 7.00/7.00% (\$\$)	2,386.76	735.00	1,651.76	69.21
Nett Amount (\$\$)	36,483.40	11,235.00	25,248.40	69.21

INSPECTION

Date of Assignment:	24/06/2022	
Date Inspected:	27/06/2022	Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	7.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2022)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB4146G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,253.80 FL	*2,253.80 FL
2	2		*BONNET HINGE (LH/RH)	Not Necessary	237.40 FL	*- FL
3	1		*BONNET MOULDING	Not Necessary	41.40 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	127.30 FL	*- FL
5	1		*BONNET INSULATOR	Not Necessary	230.10 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
7	1		*RADIATOR GRILLE NEW MODEL	Mtg Cracked	1,568.60 FL	*1,568.60 FL
8	1		*FLAP ASSY ACTIVE AIR UPPER, (RH)	Mtg Broken	824.60 FL	*824.60 FL
9	1		*FRONT BUMPER COVER	Cut / Dented	481.10 FL	*481.10 FL
10	1		*FRONT BUMPER TOP COVER	Deformed / Cracked	476.30 FL	*476.30 FL
11	1		*FRONT BUMPER SPONGE	Torn	186.90 FL	*186.90 FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,136.70 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT ABSORBER (RH)	Not Necessary	186.50 FL	*- FL
14	1		*FRONT BUMPER MOULDING CENTRE UPPER	Mtg Broken / Cut	368.50 FL	*368.50 FL
15	1		*FRONT BUMPER MOULDING	Not Necessary	93.60 FL	*- FL
16	1		*FRONT BUMPER LOWER STIFFNER	Not Necessary	285.10 FL	*- FL
17	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	365.30 FL	*- FL
18	1		*FRONT BUMPER LOWER GRILLE MOULDING	Not Necessary	127.60 FL	*- FL
19	1		*FRONT BUMPER LIP	Not Necessary	35.10 FL	*- FL
20	1		*FRONT BUMPER BRACKET TOP (RH)	Broken	35.00 FL	*35.00 FL
21	1		*FRONT BUMPER BRACKET (RH)	Not Necessary	28.00 FL	*- FL
22	1		*FRONT BUMPER RETAINER MOUNTING (RH)	Not Necessary	65.30 FL	*- FL
23	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
24	1		*FRONT BUMPER GRILLE (RH)	Serviceable	186.90 FL	*- FL
25	1		*FRONT BUMPER AIR DUCT (RH)	Not Necessary	153.80 FL	*- FL
26	1		*DAY LIGHT, RH	Mtg Cracked	642.50 FL	*642.50 FL
27	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	1,139.30 FL	*1,139.30 FL
28	1		*HEADLAMP (RH)	Broken	3,987.30 FL	*2,110.30 FL
29	1		*HORN UNIT (RH)	Not Necessary	72.80 FL	*- FL
30	1		*RADIATOR INVERTER	Not Necessary	884.80 FL	*- FL
31	1		*RADIATOR	Not Necessary	710.50 FL	*- FL
32	1		*RADIATOR FAN BLOWER MOTOR ASSY	Not Necessary	1,459.60 FL	*- FL
33	1		*RADIATOR AIR GUARD (RH)	Not Necessary	76.40 FL	*- FL
34	1		*RADIATOR AIR GUARD, UPR (RH)	Not Necessary	127.50 FL	*- FL
35	1		*FRONT FENDER (RH)	Dented	490.70 FL	*490.70 FL
36	1		*FRONT FENDER APRON PANEL SIDE SUPPORT (RH)	Not Necessary	238.80 FL	*- FL
37	1		*FRONT FENDER APRON PANEL (RH)	Not Necessary	756.20 FL	*- FL
38	1		*FRONT FENDER APRON PANEL UPPER (RH)	Not Necessary	329.00 FL	*- FL
39	1		*FRONT FENDER SHIELD (RH)	Serviceable	164.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*AIRCON CONDENSER	Not Necessary	663.60 FL	*- FL
41	1		*FRONT WHEEL RIM (LH/RH)	N/SDistorted/O/SNotNecessary	2,248.40 FL	*1,124.20 FL
42	1		*FRONT WHEEL HUB ASSY (LH/RH)	N/SDamaged/O/SNotNecessary	1,357.00 FL	*678.50 FL
43	1		*FRONT WHEEL HUB CAP	N/S Cut / O/S Not Necessary	692.80 FL	*346.40 FL
44	1		*FRONT SHOCK ABSORBER (ASSY) (LH/RH)	N/SDistorted/O/SNotNecessary	745.00 FL	*372.50 FL
45	2		*FRONT SHOCK ABSORBER MOUNTING (LH/RH)	Not Necessary	745.00 FL	*- FL
46	2		*FRONT DRIVE SHAFT (LH/RH)	Not Necessary	2,273.40 FL	*- FL
47	1		*RACK & PINION ASSY	Not Necessary	2,387.40 FL	*- FL
48	2		*STG TIE END	Not Necessary	189.40 FL	*- FL
49	1		*STABILIZER BAR	Not Necessary	326.80 FL	*- FL
50	2		*STABILIZER BAR LINK	Not Necessary	184.20 FL	*- FL
51	1		*FRONT SUSPENSION LOWER ARM (LH/RH)	N/SDistorted/O/SNotNecessary	1,193.60 FL	*596.80 FL
52	1		*KNUCKLE ARM (LH/RH)	N/SDistorted/O/SNotNecessary	1,327.20 FL	*663.60 FL
53	1		*COOLANT	Not Necessary	45.00 FS	*- FS
54	1		*EMBLEM-BLUE DRIVE (RH)	Necessary	26.60 F	*26.60 FN
55	1		*FRONT TYRE (RH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	35,236.40	14,411.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,989.76	2,876.92
- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00	5.32
Total Parts (\$\$)	28,246.64	11,528.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	600.00
2	SPRAY PAINTING CHARGE	New	1,800.00	600.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	0.00
7	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
10	REMOVE / REFIX RADIATOR	New	90.00	0.00
11	REMOVE / REFIX AIRCON & REFILL GAS	New	130.00	0.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (\$\$)			5,850.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >