



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8710P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|------------------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR BUMPER COVER | CRACKED | 459.40 | 459.40 |
| 10 | REAR BUMPER CLIPS | NECESSARY | 22.00 | 22.00 |
| 1 | REAR BUMPER CENTRE MOULDING ASSY | DEFORMED | 451.25 | 451.25 |
| 1 | REAR BUMPER REINFORCEMENT | CRACKED | 394.80 | 394.80 |
| 2 | REAR BUMPER REINFORCEMENT BRACKET LH RH @ \$138.10 | NOT NECESSARY | 276.20 | - |
| 1 | REAR BUMPER FOG LAMP | NOT NECESSARY | 201.50 | - |
| 1 | REAR BUMPER LICENCE LAMP | NOT NECESSARY | 85.30 | - |
| 1 | ANTENNA ASSY SMARTKEY | NOT NECESSARY | 40.50 | - |
| 2 | REAR BUMPER SIDE BRACKET LH RH @\$55.80 | N/S BENT / O/S NOT NECESSARY | 111.60 | 55.80 |
| 1 | BOOTLID | BENT | 2,549.70 | 2,549.70 |
| 1 | BOOTLID HYUNDAI PLATE | NECESSARY | 24.30 | 24.30 |
| 1 | EMBLEM HYBRID | NECESSARY | 24.30 | 24.30 |
| 1 | EMBLEM - IONIQ | NECESSARY | 31.30 | 31.30 |
| 1 | REAR BUMPER TOWING COVER | NOT NECESSARY | 98.80 | - |
| 1 | REAR PANEL | NOT NECESSARY | 532.00 | - |
| 1 | REAR PANEL GARNISH | NOT NECESSARY | 246.80 | - |
| | LESS 20% DISCOUNT | | -1,109.95 | -802.57 |
| | | | 4,439.80 | 3,210.28 |
| <u>NETT ITEMS</u> | | | | |
| 1 | REAR NUMBER PLATE WITH TRIM COVER (N) | CRACKED | 55.00 | 55.00 |
| 1 | BOOTLID COMFORT TEL NO STICKER (N) | NECESSARY | 40.00 | 40.00 |
| 1 | BOOTLID COMFORT LOGO STICKER (N) | NECESSARY | 30.00 | 30.00 |
| 1 | BOOTLID COMFORT APP STICKER (N) | NECESSARY | 30.00 | 30.00 |
| 1 | REAR BUMPER REVERSE SENSOR (N) | NOT WORKING | 180.00 | 180.00 |
| | LESS 10% DISCOUNT | | - | -33.50 |
| | | | 335.00 | 301.50 |

Report Ref No. NS/INC22006063/Tvce2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-----------|---------------------------|-------------------|
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | REAR FENDER ADVERTISEMENT STICKER LH (SN) | NECESSARY | 100.00 | 100.00 |
| 1 | REAR FENDER ADVERTISEMENT STICKER RH (SN) | NECESSARY | 100.00 | 100.00 |
| 1 | BOOTLID ADVERTISEMENT STICKER (SN) | NECESSARY | 100.00 | 100.00 |
| | | | 300.00 | 300.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING. | | 1,100.00 | 700.00 |
| | SPRAY PAINTING CHARGE. | | 600.00 | 500.00 |
| | CHK ALL LIGHTING. | | 60.00 | 30.00 |
| | TUFF KOTE. | | 60.00 | 30.00 |
| | REMOVE / REFIX REVERSE SENSOR. | | 80.00 | 30.00 |
| | | | 1,900.00 | 1,290.00 |
| | GRAND TOTAL | | 6,974.80 | 5,101.78 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | 3,900.00 |

Report Ref No. NS/INC22006063/Tvce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.