

ASS. REC. BY: Taufik

REF:

NS/ INC 22006063/Tvc**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMF 1756K

Policy No. _____


Claims No. MT/1176534-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WPDate: _____ Person Contacted: M S b h e Vehicle: IN / OUTVeh No: SH 8710P Yr Regn: 20/9/00
Type: M.Car / M.Cycle / Bus / Van / Lorry / ② / Prime Mover /

Truck / Trailer or

Make: Hyundai C.C. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 239704 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVL*U 187051Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nih / S/Rim / STD A/Rim orTyre Size: F: 205/60K16R: u uBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/6/2022D.O.I. 15/6/22Survey held at Confort LogisDes. of Damages: Frt / ② / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP-INC-SMF1756K.29/7/22 Taufikh informed LS \$3900 (Red 2874.80, 42%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 1/8/22-typistRep. Format: TPLump Sum / E.H. (\$) \$3900Days Of Repair: 3Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE

Vehicle No. : SH8710P
 Make : HYUNDAI
 Model : IONIQ(G3)

Date: 15.06.2022
 Insurance: NTUC
 MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$459.40	cur
10	REAR BUMPER CLIPS			\$22.00	ner
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25	de
1	REAR BUMPER REINFORCEMENT			\$394.80	cur
2	REAR BUMPER REINFORCEMENT BRACKET LH RH		138.1	\$276.20	?
1	REAR BUMPER FOG LAMP			\$201.50	?
1	REAR BUMPER LICENCE LAMP			\$85.30	?
1	ANTENNA ASSY SMARTKEY			\$40.50	?
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60	?
1	BOOTLID			\$2,549.70	bt
1	BOOTLID HYUNDAI PLATE			\$24.30	ner
1	EMBLEM HYBRID			\$24.30	de
1	EMBLEM - IONIQ			\$31.30	ner
1	REAR BUMPER TOWING COVER			\$98.80	?
1	REAR PANEL			\$532.00	X
1	REAR PANEL GARNISH			\$246.80	X
	SUB TOTAL			\$5,549.75	
	LESS 20%			\$1,109.95	
	DISCOUNTED TOTAL			\$4,439.80	
	REAR FENDER ADVERTISEMENT STICKER LH			\$100.00	Nett ner
	REAR FENDER ADVERTISEMENT STICKER RH			\$100.00	Nett ner
	BOOTLID ADVERTISEMENT STICKER			\$100.00	Nett ner
	REAR NUMBER PLATE WITH TRIM COVER		-10%	\$55.00	Nett Cng
	BOOTLID COMFORT TEL NO STICKER		-10%	\$40.00	Nett ner
	BOOTLID COMFORT LOGO STICKER		10%	\$30.00	Nett ner
	BOOTLID COMFORT APP STICKER		10%	\$30.00	Nett ner
	REAR BUMPER REVERSE SENSOR		10%	\$180.00	Nett ner
				\$435.00	
	Labour Charge				
	PANEL BEATING			\$1,100.00	700
	SPRAY PAINTING CHARGE			\$600.00	500
	CHK ALL LIGHTING			\$60.00	30
	TUFF KOTE			\$60.00	30
	REMOVE/REFIX REVERSE SENSOR			\$80.00	30
	TOTAL LABOUR			\$1,900.00	
	ESTIMATE TOTAL			\$6,774.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 57495749
 up 15/6/22 @ 4:15 pm
 up Resurvey after repair
 tanpin@lkkamb.com 3 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Date/Time: 15.06.2022 14:03

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4290804


JC NO305519825

CUSTOMER R/MS CUSTOMER NO. ADDRESS TEL. (R) (P) DISCOUNT CARD NO.	COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (O)		REGN NO: SH 8710P	MILEAGE
			MAKE: HYUNDAI	FUEL E.....1/2.....F
			MODEL IONIQ(G3)	DATE/TIME IN 15.06.2022 11:10
			YR OF MANU. 25.10.2019	TARGET DATE
			CHASSIS CODE KMHC851CVLU187051	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 15.06.2022
NATURE: 3P 15.06.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

Name:
No.:
Plate No.: SH 8710P YY

Vehicle No.: SH 8710P

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard