

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/HLA22006078/KQY3M4**Date:** 31/10/2022**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP319934
<b>Claimant Vehicle No :</b>	SHC5661Z	<b>Insured Vehicle No :</b>	SND8489J
Date of Loss:	23/06/2022	Nature of Claim:	TP
		Claim No:	MPC03521/ANA

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC5661Z</b>	Engine No:	2ZR2J11626
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU703093869
Reg. Date:	26/02/2021 (Man. Year: 2020)	Odometer:	90292 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,656.45	3,087.40	2,569.05	45.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	1,130.00	3,970.00	77.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,756.45</b>	<b>4,217.40</b>	<b>6,539.05</b>	<b>60.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	752.95	295.22	457.73	60.79
<b>Nett Amount (S\$)</b>	<b>11,509.40</b>	<b>4,512.62</b>	<b>6,996.78</b>	<b>60.79</b>

**INSPECTION**

Date of Assignment:	27/06/2022		
Date Inspected:	27/06/2022	Inspected At:	TRANS-CAB AUTO SERVICES PTE LTD 58 DEFU LANE 1 SINGAPORE 539498
Estimated Period of Repair:	3.0 days		

**Adjuster:** SHIAU CHAN**Manager:** KENNETH KONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 31 Oct 2022)**Parts:** 144      TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHC5661Z)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, REAR BUMPER	Buckled	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY, REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*GUARD, REAR BUMPER, CENTER	Dented	374.50 FL	*374.50 FL
4	1		*SEAL, REAR BUMPER SIDE, LH	Serviceable	118.30 FL	*- FL
5	1		*SEAL, REAR BUMPER SIDE, RH	Serviceable	118.30 FL	*- FL
6	1		*RETAINER, REAR BUMPER SIDE, RH	Serviceable	132.60 FL	*- FL
7	1		*COVER, REAR BUMPER, LOWER	Missing	22.00 FL	*22.00 FL
8	1		*COVER, DECK TRIM, REAR	Serviceable	126.70 FL	*- FL
9	1		*PANEL SUB-ASSY, BODY LOWER BACK	Repair	651.00 FL	*- FL
10	1		*PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	Necessary	54.60 FL	*54.60 FL
11	1		*PLATE, BACK DOOR NAME, NO.1	Necessary	54.60 FL	*54.60 FL
12	1		*ORNAMENT SUB-ASSY, BACK DOOR	Necessary	47.90 FL	*47.90 FL
13	1		*GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	Mtg Cracked	913.60 FL	*913.60 FL
14	1		*BOARD ASSY, BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
15	1		*WEATHERSTRIP, BACK DOOR	Serviceable	372.30 FL	*- FL
16	1		*STAY ASSY, BACK DOOR, LH	Serviceable	242.50 FL	*- FL
17	1		*STAY ASSY, BACK DOOR, RH	Serviceable	242.50 FL	*- FL
18	1		*HINGE ASSY, BACK DOOR, LH	Repair	61.00 FL	*- FL
19	1		*HINGE ASSY, BACK DOOR, RH	Repair	61.00 FL	*- FL
20	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
21	1		*BOOT STICKER TRASCAB	Necessary	100.00 FS	*30.00 FS
22	1		*BOOT STICKER TEL NO	Necessary	100.00 FS	*30.00 FS
23	1		*SET PARKING AID	Shorted	700.00 FS	*220.00 FS
24	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
25	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
26	1		*PANEL SUB-ASSY, BACK DOOR	Bent	1,147.80 FL	*1,147.80 FL
27	1		*COVER, REAR FLOOR (CTR)	Cracked	229.90 FL	*229.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,168.60</b>	<b>4,003.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,512.15	915.80
<b>Total Parts (\$\$)</b>	<b>5,656.45</b>	<b>3,087.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,600.00	400.00
4	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	660.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,100.00</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >