

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22006085/KQY3E2

Date: 28/07/2022

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2001097849
Claimant Vehicle No : GBE8137L **Insured Vehicle No :** SMY9028B
Date of Loss: 22/06/2022 Nature of Claim: TP Claim No: 202222005357KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE8137L**
Make & Model: NISSAN NV350, 2.5 (A) Engine No: YD25394010A
Reg. Date: 31/03/2016 (Man. Year: 2016) Chassis No: JN1MC2E26Z0006464
Colour: Silver Odometer: 236887 km
Engine Capacity: 2488 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 9 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,676.20	4,078.41	3,597.79	46.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,650.00	1,550.00	48.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,876.20	5,728.41	5,147.79	47.33
Approved Total (Overridden) (S\$)		4,550.00		
Nett Amount (S\$)	10,876.20	4,550.00	6,326.20	58.17

INSPECTION

Date of Assignment: 25/06/2022
Date Inspected: 28/06/2022 Inspected At: Colour Vibe Pte. Ltd (HQ)
176 Sin Ming Drive #05-11 Sin Ming Autocare
Singapore 575721
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jul 2022)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE8137L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,101.40 F	*1,998.30 FL
2	1		*TAILGATE OUTER CHROME MOULDING	Serviceable	370.90 F	*- FL
3	1		*TAILGATE INNER LOCK	Dented	183.90 F	*183.90 FL
4	1		*TAILGATE WEATHERSTRIP (50%)	Dented / Distorted	129.30 FS	*64.65 FS
5	1		*TAILGATE LOGO	Necessary	62.50 F	*62.50 FL
6	1		*TAILGATE NV350 EMBLEM	Necessary	89.00 F	*89.00 FL
7	1		*TAILGATE URVAN EMBLEM	Necessary	75.00 F	*75.00 FL
8	2		*TAIL LAMP PANEL	Repair	649.60 F	*- FL
9	1		*REAR END PANEL	Bent	966.70 F	*247.10 FL
10	1		*REAR END PANEL INNER MEMBER	Bent	588.50 F	*460.80 FL
11	1		*REAR END PANEL INNER GARNISH	Serviceable	70.20 F	*- FL
12	1		*REAR BUMPER	Bent	899.70 F	*667.20 FL
13	2		*REAR BUMPER BRACKETS	No such part	190.00 F	*- FL
14	2		*REAR BUMPER SIDE RETAINER	Serviceable	97.00 F	*- FL
15	1		*REAR BUMPER INNER SPONGE	No such part	88.90 F	*- FL
16	1		*REAR WINDSCREEN INNER SEAL	Necessary	105.00 FS	*30.00 FS
17	1		*REAR STEP PANEL	Bent	192.60 F	*192.60 FL
18	2		*REAR NUMBER PLATE LAMP	Serviceable	108.00 F	*- FL
19	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
20	1		*REAR TAILGATE 70KM/H STICKER	Necessary	18.00 FS	*15.00 FS
21	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
22	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
23	1		*REAR REVERSE SENSOR	Dented	350.00 FS	*200.00 FS
24	1		*DECAL 6747 5028	Necessary	80.00 FS	*50.00 FS
25	1		*DECAL 8292 8821	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,676.20	4,476.05
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	397.64
Total Parts (\$\$)	7,676.20	4,078.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX INNER GARNISH	New	150.00	60.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
3	TO TRANSFER TAILGATE MECHANISM	New	80.00	60.00
4	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	200.00	120.00
5	TO APPLY UNDER COATING	New	150.00	60.00
6	PANEL BEATING, REMOVAL & REPLACEMENT ABOVE PARTS	New	1,500.00	600.00
7	TO RESPRAY PAINTING ON AFFECTED AREA	New	1,000.00	700.00
Gross Labour Cost (\$\$)			3,200.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >