

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22006088/UCY3E2

Date: 29/07/2022

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000552
Claimant Vehicle No : SNA7732D Insured Vehicle No : GZ6723M
Date of Loss: 24/06/2022 Nature of Claim: TP Claim No: IRS AISCL2022-00011FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNA7732D
Make & Model: HONDA FIT, 1.3 (A) Engine No: L13A4105449
Reg. Date: 12/09/2008 (Man. Year: 2008) Chassis No: GE61095456
Colour: Red Odometer: 165160 km
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,042.00	932.00	110.00	10.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	580.00	770.00	57.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,392.00	1,512.00	880.00	36.79
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	2,392.00	1,050.00	1,342.00	56.10
+ GST 7.00/7.00% (S\$)	167.44	73.50	93.94	56.10
Nett Amount (S\$)	2,559.44	1,123.50	1,435.94	56.10

INSPECTION

Date of Assignment: 25/06/2022 Present Location: Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected: 27/06/2022 Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines)
Blk 9006 #01-200 Tampines St 93
Singapore 528840
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2022)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA7732D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S WING MIRROR (WCP)	Damaged	320.00 F	*320.00 F
2	1		*O/S WING MIRROR COVER (WCP)	Cracked	65.00 F	*65.00 F
3	1		*O/S WING MIRROR LAMP (WCP)	Cracked	95.00 F	*95.00 F
4	1		*O/S FRONT QUARTER GLASS (WCP)	Cut	340.00 F	*340.00 F
5	1		*O/S FRONT QUARTER GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
6	1		*O/S FRONT QUARTER GLASS SEALANT	Necessary	60.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					960.00	850.00
+ Margin on L,N Items 10.00/10.00% (S\$)					82.00	82.00
Total Parts (S\$)					1,042.00	932.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUSTPROOF ACCIDENT DAMAGE AREA	New	150.00	0.00
2	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	500.00	200.00
3	TO PUTTY AND RESPRAY ACCIDENT DAMAGE AREA	New	700.00	380.00
Gross Labour Cost (\$)			1,350.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >