



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7090T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEFORMED	481.10	481.10
1	FRT FENDER LH	BENT	588.80	588.80
1	FRT FENDER LH - EMBLEM	NECESSARY	26.60	26.60
1	HEADLAMP ASSY RH	CRACKED	2,110.30	2,110.30
1	FRT BUMPER CTR MOULDING	NOT NECESSARY	368.50	-
1	FRT WHEEL CAP LH	CRACKED	346.40	346.40
1	FRT BUMPER SIDE BRACKET LH	NOT NECESSARY	41.40	-
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-797.02	-715.04
			3,188.08	2,860.16
	<u>SPECIAL NETT ITEMS</u>			
1	ADVERTISEMENT LOGO - FENDER (SN)	CUT	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	30.00
			1,500.00	910.00
	GRAND TOTAL		4,788.08	3,870.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,100.00

Report Ref No. NS/INC22006089/Tvce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.