



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 8135R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	658.00	658.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	DENTED	548.00	548.00
1	FRONT BUMPER BEAM (CONSISTENT)	NOT NECESSARY	289.00	-
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	CRACKED	128.00	128.00
1	FRONT BUMPER SIDE GRILLE COVER LH (CONSISTENT)	CRACKED	154.00	75.00
1	FRONT BUMPER LOWE GRILLE (CONSISTENT)	CRACKED	120.00	120.00
1	LH FRONT STEP GARNISH (CONSISTENT)	DEFORMED	189.00	189.00
1	LH FRONT CORNER PANEL (CONSISTENT)	DENTED	371.00	371.00
1	LH FRONT CORNER PANEL BRACKET (CONSISTENT)	CRACKED	65.00	65.00
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	598.00	-
1	BONNET HINGE (CONSISTENT)	NOT NECESSARY	154.00	-
1	FRONT WIPER TANK (CONSISTENT)	DEFORMED	195.00	195.00
1	FRONT WIPER GARNISH (CONSISTENT)	NOT NECESSARY	358.00	-
1	FRONT GRILLE (CONSISTENT)	CRACKED	384.00	384.00
1	FRONT GRILLE BASE (CONSISTENT)	CRACKED	214.00	214.00
1	FRONT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	578.00	-
1	LH FRONT HEADLAMP LOWER BRACKET (CONSISTENT)	NOT NECESSARY	41.00	-
1	LH FRONT DOOR (CONSISTENT)	DENTED	1,208.00	1,208.00
1	LH FRONT DOOR INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	445.00	-
2	LH FRONT DOOR CHECKER (CONSISTENT)	NOT NECESSARY	98.00	-
1	LH FRONT DOOR WEATHERSTRIPE (CONSISTENT)	NOT NECESSARY	154.00	-
	LESS 25% DISCOUNT		-1,737.25	-1,038.75
			5,211.75	3,116.25
<b><u>SPECIAL NETT ITEMS</u></b>				
1	LH FRONT HEADLAMP (SN) (CONSISTENT)	CRACKED	2,584.00	1,500.00
1	LH FRONT HEADLAMP OUTER GARNISH (SN) (CONSISTENT)	CUT	180.00	100.00
1	LH FRONT DOOR LTA STICKER (SN) (CONSISTENT)	NECESSARY	45.00	45.00
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	80.00	30.00
1	FRONT GRILLE CLIPS (SN) (CONSISTENT)	NECESSARY	80.00	20.00

Report Ref No. CC4/ASM22006092/Apa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
			3,014.00	1,695.00
	<b>LABOUR</b>			
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF BONNET .		1,200.00	800.00
	LABOUR FOR SPRAY PAINTING.		1,000.00	850.00
	WIRING CHECK ,		80.00	30.00
	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS .		300.00	80.00
	LABOUR FOR REMOVE & TRANSFER ALL LH DOOR FITTING.		300.00	80.00
			2,880.00	1,840.00
<b>GRAND TOTAL</b>			<b>11,105.75</b>	<b>6,651.25</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,300.00</b>

Report Ref No. CC4/ASM22006092/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.