

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006093/RCY3E2

Date: 10/08/2022

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00107372100

Claimant Vehicle No : SMB252A

Insured Vehicle No : YP5141M

Date of Loss: 23/06/2022

Nature of Claim: TP

Claim No: SNM22D204445C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB252A**

Make & Model: MAN A22, 10.5 D (A)

Engine No: 50329840142980

Reg. Date: 03/04/2012 (Man. Year: 2011)

Chassis No: WMAA22ZZ5C7001266

Colour: Multi-colour

Odometer: 861755 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Continental 8 mm

Rear Left Side: Continental 8/8 mm

Front Right Side: Continental 8 mm

Rear Right Side: Continental 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,220.00	1,970.00	250.00	11.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,890.00	1,940.00	1,950.00	50.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,110.00	3,910.00	2,200.00	36.01
+ GST 7.00/7.00% (S\$)	427.70	273.70	154.00	36.01
Nett Amount (S\$)	6,537.70	4,183.70	2,354.00	36.01

INSPECTION

Date of Assignment: 27/06/2022

Date Inspected: 27/06/2022 Inspected At:

Estimated Period of Repair: 4.0 days

TOWER TRANSIT SINGAPORE PTE LTD
(MANDAI DEPOT) (HQ)
310 Mandai Rd
Singapore 779404

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 10 Aug 2022)

Parts: N/A MAN A22 10.5 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMB252A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*OS WINDOW GLASS R5	Cracked	1,200.00 F	*1,200.00 F	
2	1		*OS FLASHER UNIT (LED)	Scratched	270.00 F	*270.00 F	
3	5		*SEALANT	Necessary	200.00 F	*200.00 F	
4	1		*ADVERTISEMENT STICKERS	Necessary	550.00 FS	*300.00 FS	
					Total Parts (S\$)	2,220.00	1,970.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE : - ITEM NOS 1-4 }	New	2,600.00	1,300.00
2	TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS : - OS BODY PANEL }	New	650.00	0.00
3	SPRAY PAINTING : - OS BODY PANEL	New	640.00	640.00
			Gross Labour Cost (S\$)	3,890.00
				1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >