

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22006097/Rcy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	01/07/2022		
	ATTN: HO WINNIE			Code:	ASM	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SND 5148M	Veh. Inspected	t	FBN 5121D	
	Policy No.	GA609444	Coverage (\$)		0.00	
	Claim No.	S2M044C0	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		27/06/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA XABRE TFX150	c.c		150	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MH3RG3710HK025629	Colour		MULTI COLOUR	
	Odometer	33826 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/70-17	MICHELIN		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-17	MICHELIN		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND REAR PORTION.			R		
5.	. General Information					
	Accident Date	14/06/2022	Inspect Date /	Time	28/06/2022 (03:09 PM)	
	Survey held at	SXZ MOTOR	-			
	61, WOODLANDS INDUSTRIAL PARK E9. #01-13. E9 PREMIUM. SINGAPORE 757047.					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM22006097/Rcy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser