

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22006100/KQY3M4**Date:** 15/03/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MW007904	
Claimant Vehicle No :	SNB5395B	Insured Vehicle No :	GBE779L	
Date of Loss:	20/06/2022	Nature of Claim:	TP	Claim No: M2203235

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB5395B	Engine No:	2ZR2M62739
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800503004
Reg. Date:	27/08/2021 (Man. Year: 2021)	Odometer:	0 km
Colour:	Metallic Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 2 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,147.75	7,807.15	6,340.60	44.82
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	4,250.00	2,710.00	1,540.00	36.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,408.75	10,528.15	7,880.60	42.81
+ GST 7.00/7.00% (S\$)	1,288.61	736.97	551.64	42.81
Nett Amount (S\$)	19,697.36	11,265.12	8,432.24	42.81

INSPECTION

Date of Assignment:	27/06/2022	COMFORTDELGRO ENGINEERING PTE LTD
Date Inspected:	28/06/2022	205 BRADDELL ROAD
Inspected At:		BLK C, 3RD FLOOR
		SINGAPORE 579701.
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB5395B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH FENDER	Bent	1,116.00 FL	*911.20 FL
2	1		*FRT LH FENDER INNER SHIELD	Deformed	181.00 FL	*181.00 FL
3	8		*FRT LH FENDER INNER SHIELD CLIP	Necessary	44.00 FL	*44.00 FL
4	1		*FRT LH FENDER QUARTER GLASS	Serviceable	633.00 FL	*- FL
5	1		*FRT LH FENDER QUARTER GLASS SEALANT	Not Necessary	40.00 FS	*- FS
6	1		*FRT LH DOOR	Bent	1,744.00 FL	*1,744.00 FL
7	1		*FRT LH DOOR HINGE TOP	Bent	104.00 FL	*104.00 FL
8	1		*FRT LH DOOR HINGE LOWER	Bent	118.00 FL	*118.00 FL
9	1		*FRT LH DOOR CHECKER	Serviceable	196.00 FL	*- FL
10	1		*LH WING MIRROR ASSY	Broken	1,011.00 FL	*1,011.00 FL
11	1		*FRT LH DOOR OUTER MOULDING	Buckled	111.00 FL	*111.00 FL
12	1		*FRT LH DOOR FRAME STICKER (VERTICAL FRT)	Necessary	30.00 FL	*30.00 FL
13	1		*FRT LH DOOR FRAME STICKER (VERTICAL REAR)	Necessary	59.00 FL	*59.00 FL
14	1		*FRT LH DOOR FRAME STICKER TOP	Necessary	42.00 FL	*42.00 FL
15	1		*FRT LH DOOR WEATHER STRIP	Serviceable	329.00 FL	*- FL
16	1		*FRT LH DOOR LOCK MECHANISM	Jammed	596.00 FL	*596.00 FL
17	1		*FRT LH DOOR LOWER INNER RUBBER SEAL	Serviceable	96.00 FL	*- FL
18	1		*FRT LH DOOR GLASS	Cut	633.00 FL	*633.00 FL
19	1		*FRT LH DOOR GLASS SOLAR FILM	Necessary	200.00 FS	*100.00 FS
20	1		*FRT LH DOOR GLASS RUN CHANNEL	Serviceable	274.00 FS	*- FS
21	1		*FRT LH DOOR OUTER HANDLE	Broken	415.00 FL	*415.00 FL
22	1		*FRT LH DOOR HANDLE SENSOR	Cracked	25.00 FL	*25.00 FL
23	1		*FRT LH DOOR HANDLE SEAL 1	Necessary	18.00 FL	*18.00 FL
24	1		*FRT LH DOOR HANDLE SEAL 2	Necessary	18.00 FL	*18.00 FL
25	1		*LH CENTER PILLAR OUTER	Repair	304.00 FS	*- FS
26	1		*LH PILLAR CHASSIS STICKER	Not Necessary	60.00 FS	*- FS
27	1		*LH SLIDING DOOR	Bent	1,927.00 FL	*1,594.00 FL
28	1		*LH SLIDING DOOR OUTER HANDLE	Jammed	157.00 FL	*157.00 FL
29	1		*LH SLIDING DOOR PRESS BUTTON SENSOR	Dented	161.00 FL	*161.00 FL
30	1		*LH SLIDING DOOR FRT VERTICAL SENSOR MOULDING	Cut	1,372.00 FL	*1,372.00 FL
31	1		*LH SLIDING DOOR GLASS MOULDING	Buckled	105.00 FL	*105.00 FL
32	1		*LH SLIDING DOOR VERTICAL BLACK STICKER	Necessary	51.00 FL	*51.00 FL
33	1		*LH SLIDING DOOR TOP BLACK STICKER	Necessary	50.00 FL	*50.00 FL
34	1		*LH SLIDING DOOR LOCK MECHANISM	Repair	254.00 FS	*- FS
35	1		*LH SLIDING DOOR GLASS REGULATOR	Serviceable	337.00 FL	*- FL
36	1		*LH SLIDING DOOR BODY WEATHER STRIP	Serviceable	109.00 FS	*- FS
37	1		*LH SLIDING DOOR AUTO DR MOTOR	Serviceable	4,664.00 FL	*- FL
38	1		*LH SLIDING DOOR LOWER ROLLER	Serviceable	140.00 FL	*- FL
39	1		*FRT LH DOOR HANDLE INNER BRACKET	Cracked	144.00 FL	*144.00 FL
40	1		*REAR LH SLIDING DOOR HANDLE INNER BRACKET	Cracked	167.00 FL	*167.00 FL
41	1		*REAR LH SLIDING DOOR HANDLE RUBBER SEAL 1	Necessary	18.00 FL	*18.00 FL
42	1		*REAR LH SLIDING DOOR HANDLE RUBBER SEAL 2	Necessary	18.00 FL	*18.00 FL
43	1		*LH FRT FENDER INNER COVER	Cracked	118.00 FL	*118.00 FL
44	1		*WING MIRROR OUTER COVER LH	Dented	103.00 FL	*103.00 FL
45	1		*FRONT DOOR LH SWITCH	Shorted	28.00 FL	*28.00 FL
46	1		*LH SLIDING DOOR MOULDING	Necessary	130.00 FL	*130.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					18,450.00	10,376.20
- List Item Discount on L Items 25.00/25.00% (S\$)					4,302.25	2,569.05
Total Parts (S\$)					14,147.75	7,807.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP CASE (INSURER)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT ,WELD ON LH CENTER PILLAR,JACK,STRAIGHTEN ON FRT LH A PILLAR,LH REAR SIDE PANEL,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1,800.00	1,000.00
2	TO PUTTY,RESPRAY ON LH FRT FENDER,A PILLAR,FRT LH DOOR ,CENTER PILLAR,SLIDING DOOR,LH SIDE REAR PANEL,LH WINGMIRROR AND EFFECTED AREAS	New	1,600.00	1,250.00
3	TO TRANSFER LH DOOR PART TO NEW DOOR	New	150.00	80.00
4	TO TRANSFER LH SLIDING DOOR PARTS TO NEW DOOR	New	250.00	100.00
5	TO REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR AND REFIT	New	120.00	80.00
6	CHECK LIGHTING AND WIRING	New	30.00	20.00
7	TO REPROGRAM LH SLIDING DOOR AFTER RENEW	New	300.00	180.00
Gross Labour Cost (\$\$)			4,250.00	2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >