

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22006103/UCY3M4**Date:** 25/07/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SLX1673H **Insured Vehicle No :** SDE3083S

Date of Loss: 22/06/2022 Nature of Claim: TP Claim No: DMPC2200257H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX1673H**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: LEB5962012

Reg. Date: 19/03/2018 (Man. Year: 2017) Chassis No: RU31261995

Colour: Blue Odometer: 55883 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,340.04	2,813.48	4,526.56	61.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,450.00	1,480.00	50.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,270.04	4,263.48	6,006.56	58.49
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	10,270.04	3,400.00	6,870.04	66.89
+ GST 7.00/7.00% (S\$)	718.90	238.00	480.90	66.89
Nett Amount (S\$)	10,988.94	3,638.00	7,350.94	66.89

INSPECTION

Date of Assignment: 27/06/2022

Date Inspected: 28/06/2022 Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ)
1 KAKI BUKIT AVE 6, #02-47 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX1673H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,287.10 FL	*997.30 FL
2	1		*SET TAILGATE GLASS MOULDING	Necessary	121.20 FL	*121.20 FL
3	1		*TAILGATE LOGO	Not Necessary	48.60 FL	*- FL
4	1		*TAILGATE EMBLEM VEZEL	Necessary	58.60 FL	*58.60 FL
5	1		*TAILGATE EMBLEM HYBRID	Necessary	62.20 FL	*62.20 FL
6	1		*TAILGATE OUTER GARNISH	Not Necessary	391.40 FL	*- FL
7	1		*TAILGATE LAMPS - LH	Cracked	470.30 FL	*280.40 FL
8	1		*TAILGATE INNER LOCK	Not Necessary	280.90 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	486.90 FL	*- FL
10	1		*TAILGATE W/STRIP	Not Necessary	198.70 FL	*- FL
11	2		*TAILGATE STOPPER	Not Necessary	24.40 FL	*- FL
12	1		*TAILLAMPS - LH	Cracked	528.10 FL	*528.10 FL
13	1		*REAR BUMPER	Dented	891.60 FL	*891.60 FL
14	1		*REAR BUMPER REFELCTOR - LH	Cracked	171.20 FL	*171.20 FL
15	1		*REAR BUMPER SIDE - LH	Not Necessary	241.60 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINERS - RH/LH	Not Necessary	97.20 FL	*- FL
17	1		*REAR END PANEL	Repair	759.10 FL	*- FL
18	1		*REAR END PANEL GARNISH	Not Necessary	241.20 FL	*- FL
19	1		*REAR FLOOR BOARD	Not Necessary	370.60 FL	*- FL
20	1		*REAR FLOOR TRAY	Not Necessary	361.80 FL	*- FL
21	1		*REAR FLOOR UNDERCOVER	Not Necessary	241.20 FL	*- FL
22	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	191.20 FL	*- FL
23	1		*REAR SMART KEYLESS BUZZEL	Not Necessary	196.80 FL	*- FL
24	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	671.90 FL	*- FL
25	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
26	1		*SET TAILGATE GLASS FOAM TAPE	Necessary	60.00 FS	*40.00 FS
27	1		*SET TAILGATE OUTER GARNISH CLIP	Not Necessary	80.00 FS	*- FS
28	1		*SET TAILGATE TOP SPOILER CLIP	Not Necessary	80.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
30	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,018.80	3,435.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,678.76	622.12
Total Parts (\$\$)	7,340.04	2,813.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT & REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE & REPLACE TAILGATE GLASS	New	180.00	120.00
3	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	80.00
4	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS	New	80.00	50.00
5	TO TUFF KOTE	New	100.00	30.00
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	New	1,200.00	600.00
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	New	1,200.00	550.00
Gross Labour Cost (\$)			2,930.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >