

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22006105/AVY3Q2**Date:** 07/10/2022REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SMM2979R	Insured Vehicle No :	SGM1516X
Date of Loss:	24/06/2022	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM2979R	Engine No:	1NZR754075
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Chassis No:	NHP1707161896
Reg. Date:	25/06/2019 (Man. Year: 2019)	Odometer:	32705 km
Colour:	Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	SUNWIDE 6 mm	Rear Left Side:	SUNWIDE 6 mm
Front Right Side:	SUNWIDE 6 mm	Rear Right Side:	SUNWIDE 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,238.35	4,989.82	8,248.53	62.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	1,250.00	3,070.00	71.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,558.35	6,239.82	11,318.53	64.46
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	17,558.35	5,000.00	12,558.35	71.52

INSPECTION

Date of Assignment:	27/06/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	27/06/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2022)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM2979R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,425.00 FL	*581.00 FL
2	1		*FRONT BUMPER GRILLE	Not Necessary	495.00 FL	*- FL
3	1		*FRONT BUMPER GRILLE CHROME	Not Necessary	285.00 FL	*- FL
4	1		*FRONT BUMPER SIDE GRILLE GARNISH RH	Cut	134.20 FL	*134.20 FL
5	1		*FRONT BUMPER SIDE RETAINER	N/S Cracked	130.40 FL	*65.20 FL
6	1		*FRONT BUMPER SPONGE	Cracked	295.00 FL	*137.00 FL
7	1		*FRONT BUMPER UNDER COVER GARNISH	Not Necessary	265.00 FL	*- FL
8	1		*HEADLAMP LH	Cut	1,970.00 FL	*1,970.00 FL
9	1		*FRONT GRILLE	Not Necessary	495.00 FL	*- FL
10	1		*FRONT GRILLE LOGO	Not Necessary	90.00 FL	*- FL
11	1		*FRONT GRILLE TOP CHROME	Not Necessary	68.00 FL	*- FL
12	1		*FRONT FENDER LH	Buckled	795.00 FL	*795.00 FL
13	1		*FRONT FENDER EMBLEM HYBRID LH	Necessary	285.00 FL	*285.00 FL
14	1		*FRONT FENDER INNER COWLING LH	Torn	195.00 FL	*195.00 FL
15	1		*FRONT WHEEL HOUSE EXTEND PANEL LH	Not Necessary	702.10 FL	*- FL
16	1		*FRONT ABS SENSOR LH	Not Necessary	398.00 FL	*- FL
17	1		*FRONT KNUCKLE ARM BEARING LH	Damaged	686.20 FL	*237.00 FL
18	1		*FRONT STABILIZER BAR LINKAGE LH	Not Necessary	270.30 FL	*- FL
19	1		*FRONT SHOCK ABSORBER LH	Damaged	517.00 FL	*436.00 FL
20	1		*FRONT KNUCKLE ARM LH	Damaged	600.70 FL	*600.70 FL
21	1		*FRONT LOWER ARM LH	Bent	1,188.90 FL	*497.00 FL
22	1		*FRONT DRIVESHAFT LH	Not Necessary	1,511.60 FL	*- FL
23	1		*FRONT STEERING RACK AND PINION	Not Necessary	1,955.40 FL	*- FL
24	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
25	1		*SET FRONT WIPER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
26	1		*SET FRONT GRILLE CLIP	Not Necessary	50.00 FS	*- FS
27	1		*FRONT SUPPORT PANEL TOP COVER GARNISH (CLIP)	Not Necessary	60.00 FS	*- FS
28	1		*FRONT SUPPORT PANEL BOTTOM COVER GARNISH	Not Necessary	60.00 FS	*- FS
29	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	80.00 FS	*30.00 FS
30	1		*FRONT WHEEL RIM LH	Cut	1,200.00 FS	*480.00 FS
31	1		*FRONT WHEEL TYRE LH	Not Necessary	550.00 FS	*- FS
32	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,927.80	6,473.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,689.45	1,483.28
Total Parts (\$\$)	13,238.35	4,989.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,200.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	400.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	80.00	30.00
5	REFOCUS HEADLAMP BEAM	New	60.00	0.00
6	REMOVE AND REFIX STEERING RACK PINION	New	350.00	0.00
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	200.00
8	TO PRESS FRONT WHEEL BEARING	New	80.00	0.00
9	FOUR WHEEL ALIGNMENT	New	120.00	80.00
10	RESET ABS LIGHT	New	350.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATIONETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,320.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >