



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22006114/Ecy3m4 Date: 28/09/2022 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBB 29J	Veh. Inspected	XD 8373R	
Policy No.	D-22099208MFCV/14	Coverage (\$)	0.00	
Claim No.	D22001551MFCV	Excess (\$)	0.00	
Assign From	AINI BINTE	Assign Date	27/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLVO FEE300	c.c	7146	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	YV2VH70D6EB670194	Colour	WHITE	
Odometer	420564 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	SAILUN	4 mm	
L/H Front Tyre	295/80 R22.5	SAILUN	4 mm	
R/H Rear Tyre	295/80 R22.5	SAILUN	4 mm	
L/H Rear Tyre	295/80 R22.5	SAILUN	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/05/2022	Inspection Date	29/06/2022	
Survey held at	UD TRUCKS SINGAPORE (PTE.) LTD 12 TUAS AVENUE 10, SINGAPORE 639136			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	