

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22006116/ANY3M4**Date:** 18/07/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBA4753E **Insured Vehicle No :** GX4539C
 Date of Loss: 21/06/2022 Nature of Claim: TP Claim No: CDMCG22001209

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA4753E**
 Make & Model: TOYOTA DYNA 100 MANUAL, 3.0 D (M) Engine No: 1KD1661855
 Reg. Date: 27/07/2007 (Man. Year: 2007) Chassis No: JTFNT24Y705000144
 Colour: Silver Odometer: 536303 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C
 Front Left Side: Condor 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: Condor 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,236.79	1,035.80	3,200.99	75.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,450.00	570.00	28.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,256.79	2,485.80	3,770.99	60.27
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	6,256.79	1,900.00	4,356.79	69.63
+ GST 7.00/7.00% (S\$)	437.98	133.00	304.98	69.63
Nett Amount (S\$)	6,694.77	2,033.00	4,661.77	69.63

INSPECTION

Date of Assignment: 27/06/2022
 Date Inspected: 29/06/2022 Inspected At: KAI MOTOR TRADING (HQ)
 BLK 3007 UBI ROAD 1, #01-440
 Singapore 408701
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 18 Jul 2022)	
Parts:	N/A	TOYOTA DYNA 100 MANUAL 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA4753E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Repair	1,607.35 FL	*- FL
2	1		*FRONT DOOR HINGE TOP	Not Necessary	74.10 FL	*- FL
3	1		*FRONT DOOR HINGE LOWER	Not Necessary	74.10 FL	*- FL
4	1		*FRONT SIDE CORNER PANEL LH	Dented	258.10 FL	*258.10 FL
5	1		*FRONT PANEL	Dented	853.10 FL	*853.10 FL
6	1		*FRONT SIDE PANEL GARNISH	Not Necessary	66.90 FL	*- FL
7	1		*HEAD LAMP LH	Not Necessary	696.10 FL	*- FL
8	1		*FRONT BUMPER	Repair	461.10 FL	*- FL
9	1		*FRONT GRILLE	Not Necessary	258.95 FL	*- FL
10	1		*FRONT PANEL LOGO	Necessary	74.10 FL	*74.10 FL
11	1		*FRONT SIDE DYNA PLATE	Necessary	69.10 FL	*69.10 FL
12	1		*FRONT DOOR STICKER	Necessary	108.09 FS	*35.00 FS
13	1		*WINDSCREEN GLASS SEALANT	Necessary	85.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,686.09	1,349.40
- List Item Discount on L Items 10.00/25.00% (S\$)	449.30	313.60
Total Parts (S\$)	4,236.79	1,035.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY	New	850.00	600.00
2	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	950.00	700.00
3	TO REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	120.00	120.00
4	TO CHECK WIRING FUNCTIONS	New	100.00	30.00
			Gross Labour Cost (\$)	2,020.00
				1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >