

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006117/ACY3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00100092102
<b>Claimant Vehicle No :</b>	SLF4962Z	<b>Insured Vehicle No :</b>	YN6686L
Date of Loss:	18/06/2022	Nature of Claim:	TP
		Claim No:	SNM22D204299/C02/CSC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLF4962Z</b>	Engine No:	3ZRB833834
Make & Model:	TOYOTA HARRIER, 2.0 Premium (A)	Chassis No:	ZSU600084029
Reg. Date:	29/08/2016 (Man. Year: 2016)	Odometer:	89888 km
Colour:	White		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,060.77	3,270.75	6,790.02	67.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	730.00	670.00	47.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,460.77</b>	<b>4,000.75</b>	<b>7,460.02</b>	<b>65.09</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,200.00</b>		
<b>Nett Amount (\$\$)</b>	<b>11,460.77</b>	<b>3,200.00</b>	<b>8,260.77</b>	<b>72.08</b>

**INSPECTION**

Date of Assignment:	11/04/2023	1st Automotive Services Pte Ltd (HQ) 8 Kaki Bukit Avenue 4 Premier, @ Kaki Bukit Office @ #01-49  Ws @ #01-51 & 52 Singapore 415875
Date Inspected:	28/06/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF4962Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	911.30 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	125.50 FL	*- FL
3	1		*HEADLAMP RH	Cut	7,814.50 FL	*3,512.00 FL
4	1		*FRONT FENDER RH	Dented	1,556.40 FL	*849.00 FL
5	1		*FRONT FENDER INNER PANEL RH	Not Necessary	984.00 FL	*- FL
6	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	556.00 FL	*- FL
7	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
8	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
9	1		*FRONT RIMS RH	Not Necessary	1,000.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					13,047.70	4,361.00
- List Item Discount on L Items 25.00/25.00% (S\$)					2,986.93	1,090.25
Total Parts (S\$)					10,060.77	3,270.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	30.00
2	PANEL BEATING ON AFFECTED AREA	New	600.00	300.00
3	SPRAY PAINTING ON AFFECTED AREA	New	600.00	400.00
4	APPLY ANTI RUST ON AFFECTED AREA	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,400.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >