

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 70H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DENTED / CRACKED	551.00	531.00
1	FRONT BUMPER SIDE RETAINER R/H	SERVICEABLE	58.00	-
1	FRONT BUMPER FOGLAMP COVER RH	SERVICEABLE	65.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	108.00	-
1	FRONT BUMPER INNER FOAM	SERVICEABLE	95.00	-
1	HEADLAMP ASSY RH	SERVICEABLE	2,200.00	-
1	HEADLAMP MOULDING RH	SERVICEABLE	200.00	-
	LESS 25% DISCOUNT		-819.25	-132.75
			2,457.75	398.25
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN FRONT PANELS WHERE NECESSARY AND REPLACE ABOVE PARTS.		500.00	200.00
	PUTTY AND SPRAY PAINT ACCIDENT AFFECTED AREAS (PEARL WHITE).		500.00	220.00
			1,000.00	420.00
	GRAND TOTAL		3,497.75	858.25

RECOMMENDED COST OF REPAIRS			858.25
-----------------------------	--	--	--------

Report Ref No. CS/SPF22006119/Kvy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$800.00-\$900.00

RECOMMENDED REPAIR DAYS: 2

WEEKEND: 0 TOTAL DAYS: 2

KONG SENG CHEONG

Licensed Appraiser