

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22006121/EYA3Q2**Date:** 19/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414-02

Claimant Vehicle No : SMH81U **Insured Vehicle No :** SND5080Z

Date of Loss: 23/06/2022 Nature of Claim: TP Claim No: MFL2022D0003578

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH81U**
 Make & Model: PORSCHE MACAN II, 2.0 PDK E6 (A) Engine No: 018177
 Reg. Date: 23/08/2019 (Man. Year: 2019) Chassis No: WP1ZZZ95ZKLB21026
 Colour: Black Odometer: 30493 km
 Engine Capacity: 2995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/35 R21 Rear Tyre Size: 295/35 R21
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,374.90	5,103.10	4,271.80	45.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,260.00	6,440.00	3,820.00	37.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,634.90	11,543.10	8,091.80	41.21
+ GST 7.00/7.00% (S\$)	1,374.44	808.02	566.42	41.21
Nett Amount (S\$)	21,009.34	12,351.12	8,658.22	41.21
+ Loss of Use (6.0 x S\$180.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		1,550.00		
Nett Liability (S\$)		14,988.57		

INSPECTION

Date of Assignment: 27/06/2022

Date Inspected: 30/06/2022

Inspected At:

Eurokars Auto Pte Ltd (HQ)
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2023)
Parts:	M1-SUV	PORSCHE MACAN II 2.0 PDK E6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH81U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,155.80 F	*- F
2	1		*SENSOR GASKET	Necessary	13.20 F	*13.20 F
3	1		*WHEEL COVER FLAP LH	Cut	50.90 F	*50.90 F
4	8		*EXPANSION RIVET	Necessary	4.80 F	*4.80 F
5	4		*EXPANDER NUT	Necessary	9.20 F	*9.20 F
6	1		*REAR DOOR LH	Repair	2,203.40 F	*- F
7	1		*DOOR CHECKER	Not Necessary	113.40 F	*- F
8	2		*HEXAGON SOCKET HEAD BOLT	Not Necessary	3.80 F	*- F
9	1		*CAMBINATION SCREW	Not Necessary	2.50 F	*- F
10	1		*DOOR SEAL OUTER LH	Not Necessary	248.60 F	*- F
11	1		*DOOR SEAL C -PILLAR	Not Necessary	190.80 F	*- F
12	4		*GASKET	Not Necessary	5.20 F	*- F
13	2		*STOPPER	Not Necessary	14.80 F	*- F
14	1		*INSULATION	Not Necessary	10.90 F	*- F
15	6		*CLIP	Not Necessary	6.60 F	*- F
16	1		*P958-537-437-40-(WH17) ADHESIVE TAPE DO	Not Necessary	132.40 F	*- F
17	2		*COMBINATION SCREW (WH03)	Not Necessary	6.20 F	*- F
18	6		*SCREW	Not Necessary	7.80 F	*- F
19	1		*CAVITY PRESERVATION (AKA3)	Not Necessary	72.40 F	*- F
20	1		*P000-043-207-67/SEALANT (W736)	Not Necessary	67.20 F	*- F
21	1		*REAR DOOR LOWER TRIM GARNISH	Necessary	586.70 F	*586.70 F
22	1		*REPAIR KIT	Necessary	113.10 F	*113.10 F
23	1		*ALLOY WHEEL TITANIUM	Cut	4,305.20 F	*4,305.20 F
24	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					9,374.90	5,103.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE /REPLACE REAR BUMPER ,REAR DOOR LH & ALL ACCIDENT DAMAGED BODY PARTS .TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	4,680.00	2,340.00
2	TO RESPRAY REAR BUMPER ,REAR DOOR LH	New	2,600.00	2,400.00
3	TO CARRY OUT BODY CAVITY PRESERVATION	New	250.00	0.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	680.00	680.00
6	TO TRANSFER THE REAR DOOR LH MECHANISM	New	780.00	0.00
7	TO INSTALL THE BODY WRAP PROTECTION STICKER (NPA)	New	0.00	0.00
8	TO TRANSFER THE REVERSE SENSORS	New	300.00	150.00
9	TO APPLY SPECIAL CLERAMIC COATING (NPA)	New	0.00	0.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
Gross Labour Cost (S\$)			10,260.00	6,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >