

Steve

CC4/1197 006121/003

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMH 814 Yr Regn: 23/8/19
 Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Porsche Macan c.c. 2995
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 30493 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WPI227952KLB 21026
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 295/35R21
 R: 1
☒ ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 9/3/19 D.O.I. 30/6/19
 Survey held at Trans Europe
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear LH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MR- 300K</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.A. (%)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

INDIA INT'L INSURANCE PTE LTD		NAME :		WIP : 32399	
64 CECIL STREET #04-05		ADDRESS :		EXCESS :	
IOB BUILDING				DATE: 25-Jun-22	
SINGAPORE 049711		TEL :			
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SMH81U	DATE IN :		CONTACT PERSON :	JOBI 63310682
CHASSIS NO :	WP1ZZZ95ZKLB21026	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	Macan S	DATE REG.: 23-Aug-19		POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	1ST	SUPP	REVISED	PRICES
1	REAR BUMPER <i>X R</i>	1				\$ 1,155.80
2	SESOR GASKET <i>/ MC</i>	4				\$ 13.20
3	WHEEL COVER FLAP LH <i>/ CVT</i>	1				\$ 50.90
4	EXPANSION RIVET <i>/ MC</i>	8				\$ 4.80
5	EXPANDER NUT <i>/ MC</i>	4				\$ 9.20
6	REAR DOOR LH <i>X R</i>	1				\$ 2,203.40
7	DOOR CHECKER <i>X</i>	1				\$ 113.40
8	HEXAGON SOCKET HEAD BOLT <i>X</i>	2				\$ 3.80
9	COMBINATION SCREW <i>X</i>	1				\$ 2.50
10	DOOR SEAL OUTER LH <i>X</i>	1				\$ 248.60
11	DOOR SEAL C-PILLAR <i>X</i>	1				\$ 190.80
12	GASKET <i>X</i>	4				\$ 5.20
13	STOPPER <i>X</i>	2				\$ 14.80
14	INSULATION <i>X</i>	1				\$ 10.90
15	CLIP <i>X</i>	6				\$ 6.60
16	P958-537-437-40-/(WH17) ADHESIVE TAPE DO <i>X</i>	1				\$ 132.40
17	COMBINATION SCREW (WH03) <i>X</i>	2				\$ 6.20
18	SCREW <i>X</i>	6				\$ 7.80
19	CAVITY PRESERVATION (AKA3) <i>X</i>	1				\$ 72.40
20	P000-043-207-67-/SEALANT (W736) <i>X</i>	1				\$ 67.20
21	REAR DOOR LOWER TRIM GARNISH <i>X / MC</i>	1 <i>(photo)</i>				\$ 586.70
22	REPAIR KIT <i>X / MC</i>	1				\$ 113.10
23	ALLOY WHEEL TITANIUM <i>/ CM</i>	1				\$ 4,305.20
24		0				\$ -
TOTAL PARTS						\$ 9,324.90
						\$ -
TOTAL PARTS COST						\$ 9,324.90

SUPPLEMENTARY

NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							
3							

Labour Description				
	TO REMOVE /REPLACE REAR BUMPER, REAR DOOR LH & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560 x 1.5	2340	\$ 4,680.00
2	TO RESPRAY REAR BUMPER, REAR DOOR LH.		2400	\$ 2,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.		NETT	\$ 120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		NETT	\$ 680.00
6	TO TRANSFER THE REAR DOOR LH MECHANISM.		NETT	\$ 780.00
7	TO INSTALL THE BODY WRAP PROTECTION STICKER. (PRICE TO BE ADVISE) (quote and invoice)		NETT	
8	TO TRANSFER THE REVERSE SENSORS.			\$ 300.00
9	TO APPLY SPECIAL CERAMIC COATING. (PRICE TO BE ADVISE) (quote and invoice)		NETT	
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT	\$ 600.00
12	SUNDRIES.		NETT	\$ 50.00

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ 10,310.00
TOTAL PARTS	\$ -	\$ 9,324.90
TOTAL	\$ -	\$ 19,634.90
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ 19,634.90
GST 7%	\$ -	\$ 1,374.44
GRAND TOTAL	\$ -	\$ 21,009.34

EUROKARS AUTO PTE LTD

Authorised Signature

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature