

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22006122/AYA3Q2**Date:** 17/03/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_01

Claimant Vehicle No : SJH4751D **Insured Vehicle No :** SNB184B

Date of Loss: 26/06/2022 Nature of Claim: TP Claim No: MFL2022D0003349

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH4751D**
 Make & Model: HONDA FIT, 1.3 G (A) Engine No: L13A4107326
 Reg. Date: 08/08/2008 (Man. Year: 2008) Chassis No: GE61096832
 Colour: Red Odometer: 174591 km
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15
 Front Left Side: Viking 6 mm Rear Left Side: Viking 6 mm
 Front Right Side: Viking 6 mm Rear Right Side: Viking 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,043.00	8,083.12	2,959.88	26.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	3,710.00	1,240.00	25.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,993.00	11,793.12	4,199.88	26.26
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	15,993.00	8,000.00	7,993.00	49.98
+ GST 7.00/7.00% (S\$)	1,119.51	560.00	559.51	49.98
Nett Amount (S\$)	17,112.51	8,560.00	8,552.51	49.98
+ Loss of Use (15.0 x S\$60.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		38.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		9,558.45		

INSPECTION

Date of Assignment: 27/06/2022

Date Inspected: 27/06/2022 Inspected At:

Ryder Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2022)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH4751D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	581.40 FL	*495.00 FL
2	2		*REAR BUMPER O/S & N/S RETAINER	Damaged	82.40 FL	*82.40 FL
3	1		*REAR END PANEL	Dented	381.90 FL	*381.90 FL
4	2		*REAR O/S & N/S STAY	Not Necessary	154.20 FL	*- FL
5	1		*REAR END PANEL INNER TRIM	Deformed	103.50 FL	*103.50 FL
6	2		*REAR O/S & N/S TAIL LAMP	Cracked	878.20 FL	*590.00 FL
7	1		*REAR O/S & N/S TAIL LAMP PANEL	N/S Dented	363.80 FL	*181.90 FL
8	2		*REAR O/S & N/S TAIL LAMP SEALANT	Not Necessary	80.00 FL	*- FL
9	2		*REAR REGN NO PLATE LAMP	Not Necessary	107.20 FL	*- FL
10	1		*REAR BOOT COVER	Dented	871.50 FL	*871.50 FL
11	1		*REAR BOOT COVER WEATHERSTRIP	Cut	114.40 FL	*114.40 FL
12	1		*REAR BOOT COVER EMBLEM	Necessary	61.50 FL	*40.00 FL
13	1		*REAR BOOT COVER FIT EMBLEM	Necessary	61.70 FL	*45.00 FL
14	1		*REAR BOOT COVER INNER TRIM	Cracked	182.25 FL	*182.25 FL
15	4		*REAR BOOT COVER O/S & N/S STOPPER	Not Necessary	74.00 FL	*- FL
16	1		*REAR BOOT COVER MOULDING	Not Necessary	187.10 FL	*- FL
17	1		*REAR BOOT COVER LOCK (UPPER)	Damaged	291.60 FL	*291.60 FL
18	1		*REAR BOOT COVER LOCK (LOWER)	Necessary	43.10 FL	*43.10 FL
19	2		*REAR O/S & N/S FENDER INNER TRIM	Cracked	860.40 FL	*610.00 FL
20	1		*FRONT BUMPER	Deformed	580.90 FL	*485.00 FL
21	1		*FRONT BUMPER INSULATOR	Not Necessary	94.20 FL	*- FL
22	1		*FRONT BUMPER ENFORCEMENT	Dented	146.70 FL	*146.70 FL
23	2		*FRONT BUMPER O/S & N/S RETAINER	Necessary	86.60 FL	*86.60 FL
24	1		*FRONT BUMPER GRILLE (LOWER)	Necessary	196.60 FL	*196.60 FL
25	1		*FRONT GRILLE	Cracked	236.70 FL	*236.70 FL
26	1		*FRONT GRILLE EMBLEM	Necessary	71.70 FL	*45.00 FL
27	1		*FRONT BONNET	Buckled	750.30 FL	*750.30 FL
28	4		*FRONT BONNET O/S & N/S RUBBER STOPPER	Not Necessary	160.00 FL	*- FL
29	2		*FRONT O/S & N/S HEAD LAMP	Cracked	1,596.80 FL	*1,246.00 FL
30	2		*HEAD LAMP BRACKET	Cracked	82.40 FL	*82.40 FL
31	1		*FRONT SUPPORT PANEL	Buckled	696.80 FL	*696.80 FL
32	1		*FRONT BRACE PANEL	Not Necessary	269.70 FL	*- FL
33	1		*RADIATOR	Not Necessary	761.20 FL	*- FL
34	1		*CONDENSER	Warpped	810.50 FL	*810.50 FL
35	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
36	2		*REAR BUMPER SCREW CLIPS	Not Necessary	20.00 FS	*- FS
37	2		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
38	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	16.00 FS	*16.00 FS
39	11		*REAR BOOT COVER INNER TRIM CLIPS	Necessary	33.00 FS	*33.00 FS
40	4		*REAR BOOT COVER MOULDING CLIPS	Not Necessary	16.00 FS	*- FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
42	18		*REAR O/S & N/S FENDER INNER TRIM CLIPS	Necessary	54.00 FS	*54.00 FS
43	1		*REAR WINDSCREEN MOULDING	Necessary	50.00 FS	*50.00 FS
44	1		*REAR REGN NO PLATE	Not Necessary	45.00 FS	*- FS
45	10		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
46	1		*FRONT BUMPER LOWER LIP	Deformed	600.00 FS	*500.00 FS

Report was unsubmitted during this print-out.

3/17/23, 12:11 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	6		*FRONT GRILLE CLIPS	Necessary	18.00 FS	*18.00 FS
48	1		*COOLENT	Necessary	80.00 FS	*40.00 FS
49	1		*FRONT REG NO. PLATE	Not Necessary	45.00 FS	*- FS
50	1		*FRONT REG NO. PLATE BRACKET	Not Necessary	29.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					13,447.25	9,846.15
- List Item Discount on L Items 20.00/20.00% (\$\$)					2,404.25	1,763.03
Total Parts (\$\$)					11,043.00	8,083.12
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	2,200.00	1,800.00
2	TO SPRAY PAINTING	New	1,600.00	1,400.00
3	TO RE-ALIGN REAR CHASSIS FRAME	New	200.00	0.00
4	TO REMOVE & REPLACE REAR EXHAUST	New	100.00	0.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	140.00	120.00
6	TO REMOVE & REFIT REAR UPHOLSTERY TO FACILITATE REPAIR	New	50.00	50.00
7	TO REMOVE AND REPLACE REAR TAIL GATE (FITTINGS)	New	120.00	60.00
8	TO REMOVE & REPLACE RADIATOR	New	80.00	60.00
9	TO REMOVE AND REPLACE CONDENSER & TOP UP GAS	New	80.00	60.00
10	TO RE-SET ELECTRICAL SYSTEM	New	180.00	0.00
11	TO CHECK WIRING	New	100.00	60.00
12	TO RE-SEAL ANTI RUST	New	100.00	100.00
Gross Labour Cost (\$\$)			4,950.00	3,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >