

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22006123/KPA3Q2**Date:** 12/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800027071
<b>Claimant Vehicle No :</b>	SGU9403T	<b>Insured Vehicle No :</b>	GBH2182D
Date of Loss:	23/06/2022	Nature of Claim:	TP
		Claim No:	0329502027SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGU9403T</b>	Engine No:	2AR1369541
Make & Model:	TOYOTA VELLFIRE, 2.5 Z (A)	Chassis No:	AGH300040221
Reg. Date:	22/11/2016 (Man. Year: 2015)	Odometer:	171455 km
Colour:	Metallic Black		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,495.00	3,997.15	3,497.85	46.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,590.00	950.00	37.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,035.00</b>	<b>5,587.15</b>	<b>4,447.85</b>	<b>44.32</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,450.00</b>		
<b>(S\$)</b>	10,035.00	4,450.00	5,585.00	55.66
<b>+ GST 7.00/7.00% (S\$)</b>	702.45	311.50	390.95	55.66
<b>Nett Amount (S\$)</b>	<b>10,737.45</b>	<b>4,761.50</b>	<b>5,975.95</b>	<b>55.66</b>
<b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>5,363.50</b>		

INSPECTION

Date of Assignment:	27/06/2022		
Date Inspected:	27/06/2022	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	6.0 days		

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,985.00 FL	*1,718.00 FL
2	1		*REAR TAILGATE VELLFIRE EMBLEM	Necessary	88.00 FL	*88.00 FL
3	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	708.00 FL	*- FL
4	1		*REAR TAILGATE WEATHERSTRIP (50%)	Distorted / Dented	267.75 FS	*178.50 FS
5	1		*REAR WINDSCREEN MOULDING	Necessary	135.00 FL	*135.00 FL
6	1		*REAR BUMPER	Buckled	1,800.00 FL	*1,217.00 FL
7	1		*REAR BUMPER SIDE BRACKET LH	Distorted	135.00 FL	*135.00 FL
8	1		*REAR BUMPER TOWING COVER LH	Dented	40.00 FL	*40.00 FL
9	1		*REAR BUMPER REFLECTOR LH	Cracked	85.00 FL	*85.00 FL
10	1		*REAR BUMPER ANTENNA SENSOR	Cracked	85.00 FL	*85.00 FL
11	1		*REAR TAIL LAMP LOWER GARNISH COVER LH	Mtg Cracked	325.00 FL	*325.00 FL
12	1		*REAR TAIL LAMP BRACKET LH	Cracked	135.00 FL	*135.00 FL
13	1		*REAR END PANEL	Bent	798.00 FL	*745.20 FL
14	1		*REAR END PANEL UPPER COVER	Buckled	170.00 FL	*170.00 FL
15	1		*REAR FLOOR PANEL TOOLBOX UPPER BOARD	Serviceable	482.00 FL	*- FL
16	1		*REAR FENDER INNER TRIM BOARD LH	Serviceable	1,772.00 FL	*- FL
17	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
18	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
20	1		*REAR BUMPER REVERSE SENSOR	Serviceable	300.00 FS	*- FS
21	1		*REAR END PANEL JOINT SEALANT	Necessary	100.00 FS	*30.00 FS
22	1		*REAR END PANEL UPPER COVER CLIPS	Necessary	40.00 FS	*40.00 FS
23	1		*REAR FENDER INNER TRIM BOARD CLIPS LH	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					9,680.75	5,216.70
- List Item Discount on L Items 25.00/25.00% (\$\$)					2,185.75	1,219.55
Total Parts (\$\$)					7,495.00	3,997.15

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	900.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR TAIL LAMP LOWER GARNISH COVER LH ,REAR END PANEL & ETC	New	900.00	680.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC .TO EFFECT REPLACE OF REAR TAILGATE	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	60.00
7	TO DAIGNOSIS FAULT CODE & RESET MEMORY	New	120.00	0.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,540.00</b>	<b>1,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >