

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006133/APA3Q2**Date:** 17/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210148874
Claimant Vehicle No :	SMR9277K	Insured Vehicle No :	SLQ8778E
Date of Loss:	23/06/2022	Nature of Claim:	TP
		Claim No:	5039385885SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR9277K		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 COUPE AMG (A)	Engine No:	27492031590069
Reg. Date:	31/01/2020 (Man. Year: 2018)	Chassis No:	WDC2533462F494803
Colour:	Blue	Odometer:	32777 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	PETLAS 6 mm	Rear Left Side:	PETLAS 6 mm
Front Right Side:	PETLAS 6 mm	Rear Right Side:	PETLAS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,143.74	14,055.84	3,087.90	18.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,080.00	450.00	29.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,673.74	15,135.84	3,537.90	18.95
Approved Total (Overridden) (\$\$)		12,100.00		
(\$\$)	18,673.74	12,100.00	6,573.74	35.20
+ GST 7.00/7.00% (\$\$)	1,307.16	847.00	460.16	35.20
Nett Amount (\$\$)	19,980.90	12,947.00	7,033.90	35.20
+ Loss of Use (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		13,549.00		

INSPECTION

Date of Assignment:	27/06/2022	
Date Inspected:	27/06/2022	Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,450.00 FL	*2,343.00 FL
2	2		*BONNET HINGE L/R	Not Necessary	568.00 FL	*- FL
3	2		*BONNET DAMPER L/R	Not Necessary	316.00 FL	*- FL
4	1		*BONNET WEATHERSTRIP	Not Necessary	92.00 FL	*- FL
5	1		*BONNET MECHANISM LOCK	Not Necessary	132.00 FL	*- FL
6	1		*BONNET TOP HOOK LOCK	Not Necessary	65.00 FL	*- FL
7	2		*HEADLAMP ASSY L/R	Cracked	7,068.00 FL	*7,068.00 FL
8	1		*HEADLAMP BRACKET LH	Not Necessary	78.00 FL	*- FL
9	1		*FRT BUMPER ASSY	Deformed	2,270.00 FL	*1,915.00 FL
10	10		*FRT BUMPER CLIPS	Necessary	95.00 FL	*50.00 FL
11	2		*FRT BUMPER BRACKET L/R	Damaged	108.60 FL	*108.60 FL
12	2		*FRT BUMPER SIDE HOLDER L/R	Not Necessary	184.00 FL	*- FL
13	1		*FRT BUMPER INNER BASE FRAME	Not Necessary	297.00 FL	*- FL
14	1		*FRT BUMPER TOW HOOK COVER	Not Necessary	105.00 FL	*- FL
15	2		*FRT BUMPER PARKING SENSOR	Not Necessary	480.00 FL	*- FL
16	1		*FRT BUMPER INNER SPONGE	Cracked	255.00 FL	*255.00 FL
17	1		*FRT BUMPER REINFORCEMENT	Bent	595.00 FL	*595.00 FL
18	1		*FRT BUMPER REINFORCEMENT BRACKET	Bent	296.00 FL	*296.00 FL
19	1		*FRT BUMPER LOWER AIR GRILLE	Cracked	190.00 FL	*190.00 FL
20	1		*FRT BUMPER LOWER EXTENSION	Cracked	210.00 FL	*210.00 FL
21	1		*FRT BUMPER LOWER GUARD LH	Not Necessary	105.00 FL	*- FL
22	1		*FRT BUMPER LOWER GUARD COVER TRIM LH	Missing	272.00 FL	*272.00 FL
23	1		*FRT FOG LAMP COVER LH	Deformed	130.00 FL	*130.00 FL
24	1		*FRT GRILLE ASSY	Cracked	1,348.00 FL	*1,348.00 FL
25	1		*FRT GRILLE MERCEDES LOGO	Necessary	320.00 FL	*180.00 FL
26	1		*FRT GRILLE CHROME TRIM	Cut	518.00 FL	*350.00 FL
27	1		*FRT GRILLE BRACKET	Not Necessary	92.00 FL	*- FL
28	1		*RADIATOR SIDE AIR GUIDE L/R	N/S Deformed	204.00 FL	*102.00 FL
29	1		*FRT NO PLATE BASE	Deformed	155.00 FL	*155.00 FL
30	1		*SET FRT NO PLATE W/FRAME	Damaged	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,043.60	15,612.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,899.86	1,556.76
Total Parts (\$\$)	17,143.74	14,055.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	80.00	30.00
2	TO REMOVE REPAIR AND REPLACED DAMAGED BODYPARTS REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	650.00	550.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	800.00	500.00
Gross Labour Cost (S\$)			1,530.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >