5/22/23, 12:16 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS/CTI22006134/RVY3M4 Our File No:

22/05/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00126542101

TP

Claimant Vehicle

GBF9509K

Insured Vehicle No:

SJX5259T

No:

Nature of

Date of Loss:

03/06/2022

Claim:

Claim No:

SNM22D203914/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBF9509K Reg No:

Make & Model: TOYOTA HIACE, 3.0 D DX (A) Engine No: Reg. Date: 02/05/2017 (Man. Year: 2017) Chassis No:

Odometer:

1KD2698822 KDH2010219771

130390 km

Colour: Grey **Engine Capacity:**

2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Engine Modification: Pre-accident Condition: Handbrake (Serviceable): Yes No

CONDITION OF TYRES

Front Tyre Size: 195 R15C 195 R15C Rear Tyre Size: Rear Left Side: Front Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,211.50	3,009.00	202.50	6.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	740.00	1,190.00	61.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,141.50	3,749.00	1,392.50	27.08
+ GST 8.00/8.00% (S\$)	411.32	299.92	111.40	27.08
Nett Amount (S\$)	5,552.82	4,048.92	1,503.90	27.08

INSPECTION

Date of Assignment: 27/06/2022

Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Date Inspected: 07/07/2022 Inspected At:

Singapore 737856

Estimated Period of Repair: 3.0 days

MOHD RASUL Adjuster: Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS. (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$49.50 NETT)

REPAIR DETAILS

Reference

5/22/23, 12:16 PM

Part Source: (Last Synchronised: 22 May 2023)

Parts: N/A TOYOTA HIACE 3.0 D DX (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF9509K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	850.00 FL	*850.00 FL
2	1		*FRONT BUMPER BRACKET RH	* Check	55.00 FN	*- FN
3	1		*FRONT HEADLAMP RH	Scratched	1,560.00 FL	*1,560.00 FL
4	1		*FRONT DOOR RH	Bent	1,150.00 FL	*1,150.00 FL
5	1		*FRONT DOOR TOP HINGES RH	Not Necessary	85.00 FN	*- FN
6	1		*FRONT DOOR BOTTOM HINGES RH	Not Necessary	85.00 FN	*- FN
7	1		*FRONT DOOR STEP PANEL RH	Scratched	130.00 FN	*130.00 FN
8	1		*FRONT DOOR STEP PANEL GARNISH RH	Deformed	180.00 FN	*180.00 FN
9	1		*SET FRONT DOOR BODY LETTERING	Necessary	60.00 FS	*60.00 FS
F=Fra	ınchise	part. S=SpcN	lett. L=ListItemDisc. N=NettItemDisc.	-		
				Sub Total (S\$)	4,155.00	3,930.00
- List Item Discount on L Items 25.00/25.00% (S\$)				890.00	890.00	
			- Nett Item Discount on N I	tems 10.00/10.00% (S\$)	53.50	31.00
				Total Parts (S\$)	3,211.50	3,009.00
			Report was unsubmitted during	this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	50.00	30.00
2	TO TRANSFER DOOR	New	80.00	60.00
3	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,000.00	400.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION (NPA)	New	0.00	0.00
5	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	800.00	250.00
	Gross Labou	ır Cost (S\$)	1,930.00	740.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >