

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006143/UVY3M4**Date:** 08/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00033592200

Claimant Vehicle No : SMZ7158S **Insured Vehicle No :** SMH7073Y

Date of Loss: 25/06/2022 Nature of Claim: TP Claim No: SNM22D204473C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ7158S**

Make & Model: MERCEDES-BENZ GLC300, 2.0 4MATIC COUPE (R19 LED) (A) Engine No: 26492030372838

Reg. Date: 14/05/2021 (Man. Year: 2020) Chassis No: W1N2533842F924950

Colour: Grey Odometer: 38077 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 255/50 R19

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,283.81	4,049.48	5,234.33	56.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,330.00	2,480.00	65.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,093.81	5,379.48	7,714.33	58.92
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	13,093.81	4,300.00	8,793.81	67.16

INSPECTION

Date of Assignment: 28/06/2022

Date Inspected: 28/06/2022 Inspected At: Zoom Autowerks Pte Ltd (Bedok)
130 Bedok Reservoir Road, #08-1339
Singapore 470130

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jul 2022)

Parts: M1-SUV MERCEDES-BENZ GLC300 2.0 4MATIC COUPE (R19 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMZ7158S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,907.90 FL	*- FL
2	1		*REAR TAILGATE GLC 300 EMBLEM	Not Necessary	88.50 FL	*- FL
3	1		*REAR TAILGATE 4 MATIC EMBLEM	Not Necessary	88.00 FL	*- FL
4	1		*REAR TAILGATE C&C EMBLEM	Not Necessary	68.00 FL	*- FL
5	1		*REAR TAILLAMP -RH	Cracked	1,133.00 FL	*905.12 FL
6	1		*REAR END PANEL	Repair	1,016.85 FL	*- FL
7	1		*REAR END PANEL INNER GARNISH	Not Necessary	289.70 FL	*- FL
8	1		*REAR BUMPER	Distorted	2,256.90 FL	*1,533.20 FL
9	1		*REAR BUMPER LOWER BLACK GARNISH	Grazed	439.90 FL	*439.90 FL
10	1		*SET REAR BUMPER CLIP	Necessary	80.00 FL	*80.00 FL
11	1		*REAR BUMPER REFLECTOR O/S	Cracked	115.00 FL	*60.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	554.40 FL	*554.40 FL
13	1		*REAR BUMPER SIDE RETAINERS	O/s Cracked (1Piece Only)	130.00 FL	*65.00 FL
14	1		*REAR BUMPER PDC SENSORS	O/s Shorted (1Piece Only)	939.00 FL	*199.00 FL
15	1		*REAR BUMPER CHROME MOULDING - SIDE O/S	Cracked	428.00 FL	*192.30 FL
16	1		*REAR BUMPER INNER RETAINER	Cracked	455.00 FL	*288.50 FL
17	1		*REAR EXHAUST OUTER CHROME TAIL PIPE HOLDER O/S	Twisted	325.20 FL	*182.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	10,315.35	4,499.42
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,031.54	449.94
Total Parts (\$\$)	9,283.81	4,049.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	180.00	50.00
4	TO APPLY UNDERCOATING	New	150.00	0.00
5	PANEL BEATING	New	1,500.00	520.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	600.00
7	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	New	350.00	80.00
Gross Labour Cost (\$)			3,810.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >