



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

Ref: CS3/ASM22006145/Gcy3e2

8 SHENTON WAY #24-01 AXA TOWER  
SINGAPORE 068811

Date: 21/11/2022

ATTN: TEO KITTY

Code: ASM

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	SHD 3214P	<b>Veh. Inspected</b>	GBJ 1554K
<b>Policy No.</b>	VFX/P2419138	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M0458W	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	TEO KITTY	<b>Assign Date</b>	28/06/2022


### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	SUZUKI EVERY 660	<b>c.c</b>	658
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	DA17V261866	<b>Colour</b>	WHITE
<b>Odometer</b>	56294 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	155 R12	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	155 R12	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	155 R12	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	155 R12	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.	
---	---

### 5. General Information

<b>Accident Date</b>	25/06/2022	<b>Inspect Date / Time</b>	26/08/2022 ( 04:00 PM )
<b>Survey held at</b>	QAS AUTO PTE LTD 3018A UBI ROAD 1 #01-23 SINGAPORE 408711		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------

Report Ref No. CS3/ASM22006145/Gcy3e2

#### Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.