

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006147/KQY3M4**Date:** 26/07/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00241052100

**Claimant Vehicle
No :** YQ3266U**Insured Vehicle
No :** SKS7406L

Date of Loss: 20/05/2022

Nature of Claim: TP

Claim
No: SNM22D203495/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **YQ3266U**

Make & Model: HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M)

Engine No: N04CWN12814

Reg. Date: 09/02/2021 (Man. Year: 2020)

Chassis No: JHHUCV3F10K037078

Colour: White

Odometer: 80925 km

Engine Capacity: 4009 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R16

Rear Tyre Size:

195/85 R16 (D/D)

Front Left Side: Bridgestone 9 mm

Rear Left Side:

Minnell 7/7 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side:

Minnell 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	330.00	112.00	218.00	66.06
Miscellaneous Items	950.00	830.00	120.00	12.63
Labour	750.00	570.00	180.00	24.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,030.00	1,512.00	518.00	25.52
+ GST 7.00/7.00% (\$\$)	142.10	105.84	36.26	25.52
Nett Amount (\$\$)	2,172.10	1,617.84	554.26	25.52

INSPECTION

Date of Assignment: 28/06/2022 Present Location:

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 13/07/2022 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jul 2022)	
Parts:	N/A	HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ3266U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC RH TAILLAMP (TAILLAMP INSTEAD OF TAILLAMP)	Cracked	140.00 F	*140.00 FL
2	1		*1 PC RH TAILLAMP PANEL	Repair	190.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	330.00 140.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 28.00
					Total Parts (\$\$)	330.00 112.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC REAR RH MUDFLAP (Torn) (Not Consistent With The Impact)	120.00	0.00
2	1	1 PC REAR SAFETY BAR (Bent)	450.00	450.00
3	1	1 PC REAR STEP BAR (Dented)	380.00	380.00
Sub Total (\$\$)			950.00	830.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	1) TO PANEL BEATING	New	400.00	320.00
2	2) TO PUITTY AND RESPRAY PAINTING	New	350.00	250.00
Gross Labour Cost (\$\$)			750.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >