

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006149/VCY3Q2**Date:** 14/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00130042103

Claimant Vehicle No : SG6192C **Insured Vehicle No :** YM6079U

Date of Loss: 23/06/2022 Nature of Claim: TP Claim No: SNM22D204476/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG6192C**

Make & Model: MAN A95, 10.5 D (A) Engine No: 50354548025452

Reg. Date: 29/04/2021 (Man. Year: 2019) Chassis No: WMAA95ZZ5KF011779

Colour: Multi-colour Odometer: 0 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	991.00	991.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	376.00	376.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,367.00	1,367.00	0.00	0.00
+ GST 7.00/7.00% (\$\$)	95.69	95.69	0.00	0.00
Nett Amount (\$\$)	1,462.69	1,462.69	0.00	0.00

INSPECTION

Date of Assignment: 04/07/2022

Date Inspected: 28/06/2022 Inspected At: Sbs Transit Ltd (Bedok) (HQ)
1470 BEDOK NORTH AVE 4
Singapore 489946

Estimated Period of Repair: 1.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Oct 2022)	
Parts:	N/A	MAN A95 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG6192C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR ARM COMPLETE W/MIRROR N/S ES/6	Broken	991.00 F	*991.00 F
F=Franchise part.						
Total Parts (S\$)					991.00	991.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR COST (NPA)	New	0.00	0.00
2	WORKSHOP LABOUR COST	New	376.00	376.00
3	ADVERTISEMENT COST (NPA)	New	0.00	0.00
4	TOW COST (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			376.00	376.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >