

(08/11/22)

ASS. REC. BY:

thru

REF:

CS/CTI 22006149 Lucy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: Not avail

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 566192C Yr Regn: Sept 22Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN C.C. 10518Colour: Grey A/C: Insured / Std / NI / NASp. Reading: Not avail T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMAA9SZZSKFO11779Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 11r22.5R: 11r22.5BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. <u>5</u>	mm	R/Bal. <u>5</u>	mm
L/Bal. <u>5</u>	mm	L/Bal. <u>5</u>	mm
D.O.A. <u>23/6/22</u>		D.O.I. <u>28/6/22</u>	<u>1700</u>

Survey held at SBS depot (Bedok)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

rr: 500-1k
Pending estimate

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____


Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

S + RS, SI

Photos

Others

Report Format :



Accident Reference & Bus No: **AR-2022-0909 -SG6192C with YM6079U**

Activated date: Monday, 27 June 2022 09:16

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Name of Surveyor: Thevan

Company Name: LKK Auto

Date Surveyed: 28th Jun 2022

Estimate (before GST) for

Stock Code	Description	Quantity	Total Material cost (S\$)
30400000	MIRROR ARM COMPLETE W/MIRROR.N/S.E5/6	1	\$991.00
TOTAL FOR PARTS			S\$ <u>pro</u> 991.00

- ☐ Parts cost: **\$ 991.00** ✓
- ☐ Contractor Labour cost: **\$ 0.00** Xun
- ☐ Workshop Labour cost: **\$ 376.00** ✓
- ☐ Advertisement Cost: **\$ 0.00** Xun
- ☐ Repair period: **1 day** ✓

1 day
COR not finalise with w/s

- ☐ Tow Cost: **\$ 0** Xun
- ☐ Loss of use: **Not required by surveyor**
- ☐ Overheads: **Not required by surveyor**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

ie: