



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 8478P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP RH (V5C8941752B)	CUT	3,268.00	2,310.10
1	FRONT BUMPER	DISTORTED / BUCKLED	1,147.00	1,147.00
1	FRONT BUMPER SIDE BRACKET RH	DISTORTED	75.00	75.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	680.00	-
1	FRONT BUMPER ABSORBER FOAM	SERVICEABLE	99.00	-
1	FRONT FENDER RH	BENT	571.00	571.00
1	FRONT FENDER INNER SHIELD RH	SERVICEABLE	176.00	-
1	FRONT ABSORBER RH	BENT	348.00	348.00
1	FRONT CONTROL ARM RH	DISTORTED	378.00	378.00
1	FRONT KNUCKLE ARM RH	BENT	648.00	425.10
1	FRONT WHEEL BEARING RH	NECESSARY	564.00	423.00
1	FRONT BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-795.40	-567.72
			7,158.60	5,109.48
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT FENDER INNER SHIELD CLIPS RH (SN)	NOT NECESSARY	40.00	-
1	FRONT ALLOY RIM RH (SN)	DENTED	1,200.00	680.00
			1,290.00	730.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT BONNET.		700.00	400.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH & ETC.		700.00	400.00
	LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT WHEEL BEARING RH, FRONT CONTROL ARM RH & ETC.		300.00	200.00
	TO WHEEL ALIGNMENT & BALANCING.		80.00	20.00

Report Ref No. CS/AGI22006151/Kvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DIAGNOSIS FAULT CODE & RESET MEMORY.	NOT NECESSARY	120.00	-
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		100.00	20.00
			2,000.00	1,040.00
GRAND TOTAL			10,448.60	6,879.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,500.00

Report Ref No. CS/AGI22006151/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.