

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22006152/KNY3E2

**Date:** 12/07/2022

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00045152203

**Claimant Vehicle  
No :** SNB184B

**Insured  
Vehicle No :** SMJ4877D

Date of Loss: 26/06/2022

Nature of Claim: TP

Claim  
No: SNM22D204497/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB184B**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No: 2ZR2G92946

Reg. Date: 28/07/2021 (Man. Year: 2020)

Chassis No: JTDKB3FU003091946

Colour: Metallic Silver

Odometer: 96059 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 9 mm

Rear Left Side: Firenza 7 mm

Front Right Side: Sailun 9 mm

Rear Right Side: Firenza 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,151.50	6,720.65	6,430.85	48.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,540.00	2,220.00	2,320.00	51.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,691.50</b>	<b>8,940.65</b>	<b>8,750.85</b>	<b>49.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,150.00</b>		
<b>(S\$)</b>	17,691.50	7,150.00	10,541.50	59.59
<b>+ GST 7.00/7.00% (S\$)</b>	1,238.41	500.50	737.91	59.59
<b>Nett Amount (S\$)</b>	<b>18,929.91</b>	<b>7,650.50</b>	<b>11,279.41</b>	<b>59.59</b>

### INSPECTION

Date of Assignment: 28/06/2022

Date Inspected: 29/06/2022 Inspected At:

Optima Werkz Pte Ltd (HQ)  
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK  
Autopoint  
Singapore 568047

Estimated Period of Repair: 7.0 days

**Adjuster:** KENNETH KONG

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 12 Jul 2022)

**Parts:** 144      TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SNB184B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,238.00 FL	*- FL
2	1		*REAR TAILGATE OUTER GARNISH COVER	Mtg Cracked	891.00 FL	*891.00 FL
3	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	75.00 FL	*75.00 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.00 FL	*75.00 FL
5	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	251.00 FL	*- FL
6	1		*REAR TAILGATE INNER LOCK	Repair	452.00 FL	*- FL
7	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	360.00 FL	*- FL
8	1		*REAR SPOILER	Repair	1,245.00 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING	Not Necessary	95.00 FL	*- FL
10	1		*REAR TAILGATE LAMP RH	Cracked	256.00 FL	*256.00 FL
11	1		*REAR UPPER TAIL LAMP RH	Cracked	433.00 FL	*433.00 FL
12	1		*REAR LOWER TAIL LAMP RH	Cracked	486.00 FL	*486.00 FL
13	1		*REAR BUMPER	Bent	488.00 FL	*488.00 FL
14	1		*REAR BUMPER LOWER LIP	Bent	486.00 FL	*374.50 FL
15	1		*REAR BUMPER REFLECTOR RH	Scratched	60.00 FL	*60.00 FL
16	1		*REAR BUMPER SIDE BRACKET RH	Distorted	112.00 FL	*112.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	336.00 FL	*318.80 FL
18	1		*REAR BUMPER ANTENNA SENSOR	Serviceable	75.00 FL	*- FL
19	1		*REAR BUMPER TOWING COVER	Missing	25.00 FL	*25.00 FL
20	1		*REAR END PANEL	Repair	729.00 FL	*- FL
21	1		*REAR END PANEL UPPER COVER	Mtg Cracked	155.00 FL	*155.00 FL
22	1		*REAR FLOOR PANEL TOOLBOX TRAY	Serviceable	165.00 FL	*- FL
23	1		*REAR FLOOR PANEL TOOL BOX TRAY UPPER ROAD	Serviceable	504.00 FL	*- FL
24	1		*FRONT BONNET	Bent	993.00 FL	*950.50 FL
25	1		*FRONT HEADLAMP RH	Mtg Cracked	3,052.00 FL	*2,637.60 FL
26	1		*FRONT BUMPER	Bent	565.00 FL	*499.90 FL
27	1		*FRONT BUMPER TOWING COVER RH	Dented	95.00 FL	*95.00 FL
28	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	85.00 FL	*85.00 FL
29	1		*FRONT BUMPER GARNISH COVER RH	Serviceable	172.00 FL	*- FL
30	1		*FRONT BUMPER LOWER GRILLE	Serviceable	202.00 FL	*- FL
31	1		*FRONT BUMPER REINFORCEMENT	Repair	691.00 FL	*- FL
32	1		*FRONT BUMPER ABSORBER FOAM	Cracked	135.00 FL	*135.00 FL
33	1		*FRONT GRILLE	Distorted / Dented	457.00 FL	*321.90 FL
34	1		*FRONT FENDER RH	Repair	988.00 FL	*- FL
35	1		*FRONT FENDER HYBRID EMBLEM RH	Not Necessary	55.00 FL	*- FL
36	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
40	1		*REAR BUMPER REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
41	1		*REAR END PANEL JOINT SEALANT	Not Necessary	100.00 FS	*- FS
42	1		*REAR END PANEL UPPER COVER CLIPS	Not Necessary	40.00 FS	*- FS
43	1		*REAR BUMPER RUBBER MAT	Necessary	80.00 FS	*30.00 FS
44	1		*FRONT GRILLE CLIPS	Necessary	40.00 FS	*40.00 FS
45	1		*FRONT NUMBER PLATE & HOLDER	Bent	50.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Sub Total (S\$)</b>	<b>17,272.00</b>	<b>8,839.20</b>
					<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	4,120.50	2,118.55
					<b>Total Parts (S\$)</b>	<b>13,151.50</b>	<b>6,720.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
<b>Labour Items</b>					
1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC	New	2,000.00	900.00	
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR TAILGATE OUTER GARNISH COVER, REAR BUMPER, REAR END PANEL, REAR FENDER RH, FRONT BONNET, FRONT BUMPER, FRONT FENDER RH & ETC	New	1,800.00	1,200.00	
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE	New	150.00	0.00	
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS	New	120.00	0.00	
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00	
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	30.00	
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	120.00	0.00	
8	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	40.00	
			<b>Gross Labour Cost (\$\$)</b>	<b>4,540.00</b>	<b>2,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >