



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9192C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	DEFORMED	586.18	586.18
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	920.00	-
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE BRACKET RH	DEFORMED	82.30	82.30
1	HEAD LAMP PANEL RH	NOT NECESSARY	240.10	-
1	HEADLAMP RH	NOT NECESSARY	2,735.28	-
1	FRT FENDER EMBLEM RH	NECESSARY	86.50	86.50
	LESS 25% DISCOUNT		-1,168.09	-194.25
			3,504.27	582.73
	<u>LABOUR</u>			
	PANEL BEATING.		750.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.		50.00	30.00
			1,400.00	880.00
	GRAND TOTAL		4,904.27	1,462.73
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,150.00

Report Ref No. CS/SPF22006154/Tcy3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,150-\$1,400

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.