



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 2994H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED	1,171.80	1,171.80
1	REAR BUMPER CENTRE PAD	GRAZED	258.00	258.00
1	REAR BUMPER LOWER	GRAZED	600.15	600.15
1	REAR BUMPER CHROME MOULDING - O/S	NOT NECESSARY	235.00	-
1	REAR BUMPER CHROME MOULDING - CENTRE	CRACKED	271.15	271.15
1	REAR BUMPER CHROME MOULDING - N/S	NOT NECESSARY	235.00	-
1	REAR BUMPER REFLECTOR	NOT NECESSARY	55.00	-
1	REAR BUMPER PARKING SENSOR	SHORTED	182.00	182.00
1	REAR BUMPER REINFORCEMENT	DENTED	230.00	230.00
1	REAR BUMPER BEAM - PLASTIC	NOT NECESSARY	155.00	-
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	25.00	-
	LESS 10% DISCOUNT		-341.81	-271.31
			3,076.29	2,441.79
	<u>LABOUR</u>			
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	120.00	-
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		100.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		80.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		800.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		700.00	400.00
			1,800.00	770.00
	GRAND TOTAL		4,876.29	3,211.79
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00

Report Ref No. CS/AGI22006156/Ucy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.